



GOLD SHIELD INSPECTIONS

319-481-9272

office@goldshieldinspections.com


<https://www.goldshieldinspections.com>



INSPECTION REPORT

757 Roberts St
Dubuque, IA 52001

Steven Jabini
01/21/2026



Inspector

Brent Thumma

InterNACHI - Resnet - SAVE - IAC2

319-481-9272

office@goldshieldinspections.com



Agent

Kim Roush

Keller Williams Dubuque

515-205-7903

kimroush@kw.com

TABLE OF CONTENTS

1: Inspection Details	6
2: Roof Systems	10
3: Exterior	14
4: Garage	20
5: Attic	23
6: Kitchen	27
7: Bathrooms	30
8: Interior	32
9: Plumbing	36
10: Structure	42
11: Electrical	45
12: HVAC	48
13: Gold Shield Inspections Info	53
Standards of Practice	54



EXPERIENCE YOU CAN TRUST

"Click to visit our website"

Brent & Sara Thumma (319)481-9272

SUMMARY

16

MAINTENANCE OR LOW
PRIORITY

3

MATERIAL DEFECT

5

SAFETY CONCERN



EXPERIENCE YOU CAN TRUST
"Click to visit our website"

Brent Thumma (319)481-9272

-  3.3.1 Exterior - Walkways: Sidewalk, Uneven or Sunken Sections
-  3.5.1 Exterior - Exterior of Windows: Window Well Covers
-  3.8.1 Exterior - Deck, Balcony, Bridge and Porch,: General, Deck Wooden Components Needing Sealant
-  3.8.2 Exterior - Deck, Balcony, Bridge and Porch,: Exterior, Deck Support Piers, Concrete Surface Deterioration and Scaling
-  3.12.1 Exterior - Dryer vent. : Dryer Vent, Obstructed With Lint
-  3.13.1 Exterior - Retaining walls: Retaining Wall, Structural Displacement and Forward Leaning
-  4.9.1 Garage - Garage Structural: Garage, Concrete Footing, Cracked With Displacement
-  4.11.1 Garage - Garage Roof Drainage System: Drainage System Health
-  6.4.1 Kitchen - Kitchen Plumbing / Sink: Kitchen Sink, Outdated S-Trap
-  6.7.1 Kitchen - Range: Kitchen Stove, Anti-tip Not Installed
-  6.8.1 Kitchen - Range Hood or Built in Microwave: No exhaust system installed
-  7.2.1 Bathrooms - Bathroom Ventilation: Bathroom Ventilation, Dirty or Clogged Exhaust Cover
-  7.4.1 Bathrooms - Bathroom Sink: Bathroom Sink, Insufficient Water Flow
-  8.8.1 Interior - Interior Electrical: Interior Wiring, Missing Junction Box Cover
-  8.9.1 Interior - Doorbells/Detectors/Fans: Smoke Detector Install More
-  8.9.2 Interior - Doorbells/Detectors/Fans: CO Detector Needed
-  8.10.1 Interior - Laundry Room: Laundry Room, Washer Drains to Floor Drain

- 🔧 8.10.2 Interior - Laundry Room: Laundry Room Washer Supply Valve Corroded
- 🔧 9.2.1 Plumbing - Water Supply and Distribution: Corroded Pipes
- 🔧 9.2.2 Plumbing - Water Supply and Distribution: Outdated Galvanized Pipes
- 🔧 9.3.1 Plumbing - Sewage and DWV Systems: Interior, Plumbing, D-Traps Installed
- 🔧 10.4.1 Structure - Foundation: Foundation, Excessive Efflorescence
- 🔧 10.4.2 Structure - Foundation: Foundation Mortar Improper Repair Materials
- 🔧 12.2.1 HVAC - Ductwork: Ductwork, Recommend Cleaning

1: INSPECTION DETAILS

Information

Occupancy
Occupied

Home Faces
East

Temperature during inspection
Below 32(F)=0(C)



Significant precipitation in last 3 days
Yes


Type of building
Single Family (2 story)

Gold Shield Inspections



Brent & Sara Thumma
NACHI17110223 /
Anamosa, IA 52205
www.GoldShieldInspections.com
EXPERIENCE YOU CAN TRUST!

Follow us on social media, click the icons below;



Inspection Report Definitions

1. Apparent Condition: Systems and components are rated as follows:

1. **INSPECTED (IN)** Indicates that the component is functionally consistent with its original purpose but may show signs of normal wear and tear, and deterioration.
2. **Limited Inspection (LI)** Indicates that the component or system was not fully available to be inspected. Only a partial inspection could be completed.
3. **MARGINAL (MA)** These items will fall under normal lower cost home maintenance items. Indicates the component could require maintenance or replacement within 5 years.
4. **MATERIAL DEFECT (MD)** is a specific issue with a system or component of a residential property that may have a significant, adverse impact on the value of the property, or that poses an unreasonable risk to people. The fact that a system or component is near, at, or beyond the end of its normal, useful life is not, in itself, a material defect.
5. **SAFETY HAZARD (SH)** Denotes a condition that is unsafe and in need of prompt attention.

2. Installed systems and components: structural components, exterior, interior, roofing, plumbing, electrical, heating, central air-conditioning (weather permitting); insulation and ventilation.

3. Readily accessible systems and components: Only those systems and components where the inspector is not required to remove personal items, furniture, equipment, soil, snow, or other items which obstruct access or visibility.

4. Any component not listed as being deficient in some manner is assumed to be satisfactory

Important Information / Limitations: Inspection Overview

Gold Shield Inspections strives to perform all inspections in substantial compliance with the Standards of Practice as set forth by InterNACHI. As such, we inspect the readily accessible, visually observable, installed systems and components of the home as designated in these Standards of Practice. When systems or components designated in the Standards of Practice were present but were not inspected, the reason(s) the item was not inspected will be stated. This inspection is neither technically exhaustive or quantitative.

There may be comments made in this report that exceed the required reporting of the InterNACHI Standards of Practice, these comments (if present) were made as a courtesy to give you as much information as possible about the home. Exceeding the Standards of Practice will only happen when I feel I have the experience, knowledge, or evidence to do so. There should be no expectation that the Standards of Practice will be exceeded throughout the inspection, and any comments made that do exceed the standards will be followed by a recommendation for further evaluation and repairs by applicable tradespeople.

This report contains observations of those systems and components that, in my professional judgement, were not functioning properly, significantly deficient, or unsafe. **All items in this report that were designated for repair, replacement, maintenance, or further evaluation should be investigated by qualified tradespeople within the clients contingency period**, to determine a total cost of said repairs and to learn of any additional problems that may be present during these evaluations that were not visible during a "visual only" Home Inspection.

This inspection is not equal to extended day-to-day exposure and will not reveal every concern or issue that may be present, but only those significant defects that were accessible and visible at the time of inspection. This inspection can not predict future conditions, or determine if latent or concealed defects are present. The statements made in this report reflect the conditions as **existing at the time of inspection only**, and expire at the completion of the inspection. The limit of liability of Gold Shield Inspections and its employees, officers, etc. does not extend beyond the day the inspection was performed. As time and differing weather conditions may reveal deficiencies that were not present at the time of inspection, including but not limited to: roof leaks, water infiltration into crawl spaces or basements, leaks beneath sinks, tubs, and toilets, water running at toilets, the walls, doors, and flooring, may be damaged during moving, etc. Refer to the Inspection agreement regarding the scope and limitations of this inspection.

This inspection is **NOT** intended to be considered as a **GUARANTEE OR WARRANTY, EXPRESSED OR IMPLIED, regarding the operation, function, or future reliability of the home and its components. AND IT SHOULD NOT BE RELIED ON AS SUCH.** This report is only supplemental to the Sellers Disclosure and Pest (WDI) Inspection Report and should be used alongside these documents, along with quotes and advice from the tradespeople recommended in this report to gain a better understanding of the condition of the home and expected repair costs. Some risk is always involved when purchasing a property and unexpected repairs should be anticipated, as this is unfortunately, a part of home ownership. One Year Home Warranties are sometimes provided by the sellers, and are **highly recommended** as they may cover future repairs on major items and components of the home. If a warranty is not being provided by the seller(s), your Realtor can advise you of companies who offer them.

Important Information / Limitations: Notice to Third Parties

Notice to Third Parties: This report is the property of Gold Shield Inspections and is Copyrighted as of 2018. The Client(s) and their Direct Real Estate Representative named herein have been named as licensee(s) of this document. This document is non-transferrable, in whole or in part, to any and all third-parties, including; subsequent buyers, sellers, and listing agents. Copying and pasting deficiencies to prepare the repair request is permitted. THE INFORMATION IN THIS REPORT SHALL NOT BE RELIED UPON BY ANY ONE OTHER THAN THE CLIENT NAMED HEREIN. This report is governed by an Inspection agreement that contained the scope of the inspection, including limitations, exclusions, and conditions of the copyright. Unauthorized recipients are advised to contact a qualified Home Inspector of their choosing to provide them with their own Inspection and Report.

Important Information / Limitations: Items Not Inspected and Other Limitations

ITEMS NOT INSPECTED - There are items that are not inspected in a home inspection such as, but not limited to; fences and gates, pools and spas, outbuildings or any other detached structure, refrigerators, washers / dryers, storm doors and storm windows, screens, window AC units, gas furnace heat exchangers, central vacuum systems, water softeners, alarm and intercom systems, and any item that is not a permanent attached component of the home. Also drop ceiling tiles are not removed, as they are easily damaged, and this is a non-invasive inspection. Subterranean systems are also excluded, such as but not limited to: sewer lines, septic tanks, water delivery systems, and underground fuel storage tanks.

Water and gas shut off valves are not operated under any circumstances. As well, any component or appliance that is unplugged or "shut off" is not turned on or connected for the sake of evaluation. I don't have knowledge of why a component may be shut down, and can't be liable for damages that may result from activating said components/appliances.

Also not reported on are the causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; The insurability of the structure or any of its items or components, Any component or system that was not observed; Calculate the strength, adequacy, design, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility.

Important Information / Limitations: Thermal Imaging Information

THERMAL IMAGING: An infrared camera may be used for specific areas or visual problems, and should not be viewed as a full thermal scan of the entire home. Additional services are available at additional costs and would be supplemented by an additional agreement/addendum. Temperature readings displayed on thermal images in this report are included as a courtesy and should not be wholly relied upon as a home inspection is qualitative, not quantitative. These values can vary +/- 4% or more of displayed readings, and these values will display surface temperatures when air temperature readings would actually need to be conducted on some items which is beyond the scope of a home inspection. If a full thermal scan of the home is desired, please reach out to me schedule this service.

Important Information / Limitations: Other Notes - Important Info

INACCESSIBLE AREAS: In the report, there may be specific references to areas and items that were inaccessible or only partly accessible. I can make no representations regarding conditions that may be present in these areas that were concealed or inaccessible for review. With access and an opportunity for inspection, reportable conditions or hidden damage may be found in these areas.

QUALITATIVE vs QUANTITATIVE: A home inspection is not quantitative, when multiple or similar parts of a system, item, or component are found to have a deficiency, the deficiency will be noted in a qualitative manner such as "multiple present" etc. A quantitative number of deficient parts, pieces, or items will not be given as the repairing contractor will need to evaluate and ascertain the full amount or extent of the deficiency or damage. This is not a technically exhaustive inspection.

REPAIRS VERSUS UPGRADES: I inspect homes to today's safety and building standards. Therefore some recommendations made in this report may have not been required when the home was constructed. Building standards change and are improved for the safety and benefit of the occupants of the home and any repairs and/or upgrades mentioned should be considered for safety, performance, and the longevity of the homes items and components. Although, I will address some recommended upgrades in the report, this should not be construed as a full listing of items that could potentially be upgraded. To learn of ALL the ways the home could be brought up to today's building and safety standards, full and exhaustive evaluations should be conducted by qualified tradespeople.

COMPONENT LIFE EXPECTANCY: Components may be listed as having no deficiencies at the time of inspection, but may fail at any time due to their age or lack of maintenance, that couldn't be determined by the inspector. A life expectancy chart is attached to your inspection page.

PHOTOGRAPHS: Several photos are included in your inspection report. These photos are for informational purposes only and do not attempt to show every instance or occurrence of a defect.

TYPOGRAPHICAL ERRORS: This report is proofread before sending it out, but typographical errors may be present. If any errors are noticed, please feel free to contact me for clarification.

Please acknowledge to me once you have completed reading this report. At that time I will be happy to answer any questions you may have, or provide clarification. Non-acknowledgement implies that you understood all information contained in this report.

2: ROOF SYSTEMS

		IN	LI	MA	MD	SC
2.1	General Overview and Limitations of Roof Inspection	X	X			
2.2	Roof Structure/Covering	X	X			
2.3	Roof penetration	X	X			
2.4	Flashing	X	X			
2.5	Roof Drainage System	X	X			

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Roof Inspection: Inspection Method

Ground, Ladder

General Overview and Limitations of Roof Inspection: # of Layers

Unknown, Unknown

General Overview and Limitations of Roof Inspection: Primary roof-covering

Architectural Fiberglass Asphalt Shingle

General Overview and Limitations of Roof Inspection: Roof Style

Open Gable



General Overview and Limitations of Roof Inspection: Approximate Roof Covering Age

Unable to verify due to snow cover

Your inspector will use a combination of experience, knowledge of roofing materials, and specific signs of wear and tear to approximate the age of an asphalt shingle roof. Here's how a professional would go about it:

1. **Type of Shingle**: Knowing the typical lifespan of various types of asphalt shingles can provide a starting point. For example:

- **3-tab shingles**: Typically last 20-25 years.
- **Architectural shingles**: Can last 30 years or more.
- **Premium shingles**: Some can last up to 50 years.

2. **Shingle Condition**:

- **Granule Loss**: A significant loss of the granular surface on the shingle can indicate age.
- **Curling and Cupping**: The edges of older shingles often curl upwards or the middle may bubble up.
- **Cracking**: As shingles age, they become more brittle and may develop cracks.
- **Bald Spots**: Older shingles might have large areas where granules are missing.
- **Edges**: Frayed or deteriorated edges can indicate significant wear and age.

3. **Pattern of Wear**: How the shingles are wearing can give clues. For instance, if only the shingles on one side of a roof or in one area are showing wear, it might be due to external factors like overhanging trees or poor ventilation, rather than age.

4. **Moss and Algae Growth**: While this can occur on newer roofs in damp climates or shaded areas, significant growth often indicates an older roof.

5. **Underlayment and Decking Condition**: If the professional has access to inspect the underlayment or decking, they can also get clues about the roof's age. Older roofs might have felt underlayment, while newer ones might use synthetic materials.

6. **Flashing and Sealants**: The condition of flashing around vents, chimneys, and other roof penetrations can give hints. Older, corroded, or damaged flashing may indicate an older roof. Sealants that are brittle, missing, or deteriorated can also be a sign of age.

7. **Past Repairs**: Multiple layers of shingles, mismatched shingles, or evidence of numerous patches can indicate an older roof or one that's had significant issues.

Given all the above factors, a seasoned professional can often give a reasonably accurate estimate of the age of an asphalt shingle roof through visual inspection. This is an estimate based off the inspectors experience.

Roof penetration: Homeowner's Responsibility

Your job is to monitor the flashing around the plumbing vent pipes that pass through the roof surface. Sometimes they deteriorate and cause a roof leak.

Be sure that the plumbing vent pipes do not get covered, either by debris, a toy, or snow.




Flashing: Eaves and Gables

I looked for flashing installed at the eaves (near the gutter edge) and at the gables (the diagonal edge of the roof). There should be metal drip flashing material installed in these locations. The flashing helps the surface water on the roof to discharge into the gutter. Flashing also helps to prevent water intrusion under the roof-covering.

Flashing: Wall Intersections

I looked for flashing where the roof covering meets a wall or siding material. There should be step and counter flashing installed in these locations. This is not an exhaustive inspection of all flashing areas.



Roof Drainage System: Homeowner's Responsibility

Your job is to monitor the gutters and be sure that they function during and after a rainstorm. Look for loose parts, sagging gutter ends, and water leaks. The rain water should be diverted at least 4'-6' away from the house foundation/slab.

Limitations

General Overview and Limitations of Roof Inspection

LIMITED ROOF INSPECTION, SNOW AND ICE COVER

The roof inspection was limited due to snow and ice covering the surface, which restricted visibility of roofing materials, flashing, and other components. As a result, we were unable to assess the roof's overall condition, identify potential defects, or evaluate for damage. Recommend a thorough inspection of the roof by a qualified professional once the snow and ice have melted to ensure any issues are identified and addressed.

Flashing

DIFFICULT TO SEE EVERY FLASHING

I attempted to inspect the flashing related to the vent pipes, wall intersections, eaves and gables, and the roof-covering materials. In general, there should be flashing installed in certain areas where the roof covering meets something else, like a vent pipe or siding. Most flashing is not observable, because the flashing material itself is covered and hidden by the roof covering or other materials. So, it's impossible to see everything. A home inspection is a limited visual-only inspection.

3: EXTERIOR

		IN	LI	MA	MD	SC
3.1	General Overview and Limitations of Exterior Inspection	X	X			
3.2	Driveway	X	X			
3.3	Walkways	X	X			X
3.4	Exterior Doors	X				
3.5	Exterior of Windows	X		X		
3.6	General Grounds	X	X			
3.7	Soffits Facia and Trim	X				
3.8	Deck, Balcony, Bridge and Porch,	X		X	X	
3.9	Exterior Electrical	X				
3.10	Exterior Plumbing	X	X			
3.11	Exterior Stairs	X				
3.12	Dryer vent.	X		X		
3.13	Retaining walls	X	X		X	
3.14	Radon Mitigation	X				


IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Exterior Inspection: Exterior Doors:
Wood

General Overview and Limitations of Exterior Inspection: Exterior wall-covering Material
Vinyl Siding

Soffits Facia and Trim: Soffits and Fascia



Radon Mitigation: Active Radon Mitigation



General Overview and Limitations of Exterior Inspection: Homeowner's Responsibility

The exterior of your home is slowly deteriorating and aging. The sun, wind, rain and temperatures are constantly affecting it. Your job is to monitor the buildings exterior for its condition and weathertightness.

Check the condition of all exterior materials and look for developing patterns of damage or deterioration.

During a heavy rainstorm (without lightning), grab an umbrella and go outside. Walk around your house and look around at the roof and property. A rainstorm is the perfect time to see how the roof, downspouts and grading are performing. Observe the drainage patterns of your entire property, as well as the property of your neighbor. The ground around your house should slope away from all sides. Downspouts, surface gutters and drains should be directing water away from the foundation.

Driveway: Driveway Sealant

Maintenance on joints found in the driveway. Sealants eventually dry, shrink and crack, creating an avenue for water to enter the soil under the driveway. Saturation of soil under the driveway can create a variety of problems depending on soil type. The Inspector recommends that the sealant at this joint be maintained as necessary to prevent water entry.

Driveway: Common Cracks

Common cracks (1/4-inch or less) were visible in the driveway at the time of the inspection. Cracks exceeding inch should be filled with an appropriate sealant to avoid continued damage to the driveway surface from freezing moisture.

Walkways: Common Cracks

Common cracks (1/4 inch or less) were visible in the sidewalk at the time of the inspection. Cracks exceeding inch should be patched with an appropriate sealant to avoid continued damage to the walkway surface from freezing moisture.

Walkways: Maintain Walk/Wall Joint Sealant

The joint at which concrete walkways met the exterior walls was protected by a sealant. Sealants eventually dry, shrink and crack, creating an avenue for water to enter the soil next to the home foundation. Saturation of soil near the foundation can create a variety of problems depending on soil type. The Inspector recommends that the sealant at this joint be maintained as necessary to prevent water entry.

Exterior of Windows: Window Maintenance for Homeowner

Inspect and repair window gaps: Make sure that there are no gaps between your trim and exterior siding or any other area along your windows and doors. You may need to apply new caulk or remove and replace the caulk along these lines. This should be checked yearly to ensure proper sealant.

Exterior of Windows: Window Sealant

Window sealant should be removed and replaced every 5 years as part of a normal home maintenance plan.

General Grounds: Photo documentation



Deck, Balcony, Bridge and Porch,: Photo documentation



Exterior Electrical: Photo Documentation



Limitations

General Overview and Limitations of Exterior Inspection

LIMITED INSPECTION, SNOW AND ICE COVER

The inspection of exterior features, such as walkways, driveways, decks, patios, roofs, and landscaping, was limited due to snow and ice cover. This restricted visibility and access to these areas, preventing a thorough evaluation of their condition. Recommend a follow-up inspection once snow and ice have melted to assess these features and identify any potential concerns.

General Overview and Limitations of Exterior Inspection

LIMITED INSPECTION, TEMPERATURE RESTRICTION

Limited inspection on house bibs due to freezing temperatures at any point during the day. This could cause damage if ran when evening temperatures reach below freezing.



Deck, Balcony, Bridge and Porch,

LIMITED INSPECTION, DUE TO BARRIER OR LOW CLEARANCE UNDER DECK

The deck inspection was limited due to a barrier or low clearance that restricted access to the attachment point to the home and the structure beneath the deck. As a result, the condition of the ledger board, support posts, beams, and other critical structural components could not be fully evaluated. Recommend removing obstructions or consulting a qualified contractor for a more thorough inspection to confirm the deck's stability and safety.

Deficiency

3.3.1 Walkways

SIDEWALK, UNEVEN OR SUNKEN SECTIONS

 Safety Concern

Uneven or sunken sections of the driveway were observed, which may pose tripping hazards and allow water pooling. Settlement or poor subgrade preparation are common causes. Recommend leveling the affected areas, such as through mudjacking or slab replacement.



Recommendation

Contact a qualified concrete contractor.

3.5.1 Exterior of Windows

WINDOW WELL COVERS

 Maintenance or Low Priority

Recommend installation of window well covers to keep moisture and debris out of window wells.



Front Of House Windows

Recommendation

Recommended DIY Project

3.8.1 Deck, Balcony, Bridge and Porch,

GENERAL, DECK WOODEN COMPONENTS NEEDING SEALANT

 Maintenance or Low Priority



Paint Chipping

The wooden components of the deck, including the decking boards, railing, and structural supports, show signs of weathering, such as fading, discoloration, and minor surface cracking. These are indicative of the wood being exposed to the elements without adequate protection from a sealant.

Implications:

- **Moisture Penetration:** Unsealed wood absorbs water, increasing the risk of rot, decay, and fungal growth, which can weaken the structural integrity of the deck.
- **UV Damage:** Prolonged exposure to sunlight without a protective sealant accelerates wood deterioration, causing fading, splintering, and surface degradation.
- **Shortened Lifespan:** Without proper sealing, the deck's lifespan is significantly reduced, necessitating costly repairs or replacement sooner than expected.

Recommendation:

To preserve the wood's durability and appearance, it is recommended to apply a high-quality sealant or stain specifically designed for exterior wooden decks. Before applying the sealant, clean the wood thoroughly to remove dirt, mildew, and any existing finish. Ensure the wood is completely dry before sealing, as this will improve adhesion and effectiveness. Reapply the sealant as per the manufacturer's instructions, typically every 1–3 years, to maintain protection. Consult a professional contractor if further evaluation or assistance is required.

Recommendation

Contact a qualified deck contractor.

3.8.2 Deck, Balcony, Bridge and Porch,



EXTERIOR, DECK SUPPORT PIERS, CONCRETE SURFACE DETERIORATION AND SCALING

The concrete piers supporting the rear deck were observed to have significant surface scaling and deterioration. This condition is commonly caused by prolonged moisture exposure, freeze-thaw cycling, poor concrete mix, or age-related degradation, which can lead to the loss of surface material and reduced durability of the concrete. As the surface continues to break down, the structural integrity and load-bearing capacity of the piers may be adversely affected over time. While the deck appeared supported at the time of inspection, continued deterioration could result in further damage or instability. Recommend further evaluation by a qualified contractor to assess the extent of the deterioration and to determine whether repair or replacement of the affected concrete piers is needed to maintain proper support of the deck structure.

Recommendation

Contact a qualified professional.



3.12.1 Dryer vent.

**DRYER VENT, OBSTRUCTED WITH LINT**

Dryer vent was obstructed by lint produced from dryer. Recommend cleaning to get full efficiency out of your dryer.

Recommendation

Recommended DIY Project



3.13.1 Retaining walls

**RETAINING WALL, STRUCTURAL DISPLACEMENT AND FORWARD LEANING**

A retaining wall located adjacent to the garage structure was observed to be displaced and leaning forward toward the subject property. This condition is commonly associated with lateral soil pressure, inadequate drainage behind the wall, improper original construction, or long-term soil movement. The wall's proximity to the garage raises concern for potential impact on nearby structures if movement continues. At the time of inspection, it was unclear whether this retaining wall is owned by the subject property or the neighboring property, which may affect responsibility for repairs. Regardless of ownership, the observed displacement indicates a loss of structural stability, and continued movement could lead to partial or full failure. Recommend further evaluation by a qualified contractor or structural professional to assess stability, determine ownership, and establish appropriate corrective measures to reduce the risk of ongoing movement and potential damage.

Recommendation

Contact a qualified landscaping contractor



4: GARAGE

		IN	LI	MA	MD	SC
4.1	General Overview and Limitations of Garage Inspection	X	X			
4.2	Garage Overhead Door	X				
4.3	Garage Occupant Doors					
4.4	Garage Floors	X	X			
4.5	Garage Walls and Ceilings	X	X			
4.6	Garage Attic					
4.7	Garage Windows	X	X			
4.8	Garage Electrical	X	X			
4.9	Garage Structural	X	X		X	
4.10	Garage, Stairs/Steps to Living Space					
4.11	Garage Roof Drainage System	X		X		
4.12	Garage Roof	X	X			
4.13	Garage Exterior Walls	X	X			
4.14	Garage, General Grounds	X	X			

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and

Limitations of Garage Inspection:

Garage Vehicle Door Type:

Double

General Overview and

Limitations of Garage Inspection:

Number of Automatic Openers:

1

General Overview and

Limitations of Garage Inspection:

Number of Vehicle Doors:

1

Garage Overhead Door: Photo Documentation



Garage Floors: Photo documentation



General Overview and Limitations of Garage Inspection: Vehicle Door Safety:

Installed and operating correctly

Adjust Auto Reverse Safety Feature

To decrease the amount of force required to reverse the direction of the garage door, turn the knob (or screw with a screwdriver) counterclockwise one quarter. To increase the amount of force, turn it clockwise. Re-test the auto-reverse function and repeat this process until your opener is properly adjusted.

Garage Walls and Ceilings: Photo documentation



Garage, General Grounds: Photo Documentation



Limitations

General Overview and Limitations of Garage Inspection

LIMITED INSPECTION, OCCUPANTS BELONGINGS

INTERIOR ROOMS

The property was occupied at the time of inspection, and personal belongings, furniture, or stored items limited access to certain areas. As a result, a full visual inspection of all components and systems in these areas was not possible. Gold Shield Inspections cannot be held liable for any defects or issues that may exist in these inaccessible areas. We recommend a thorough review of these areas once they are cleared of belongings.

General Overview and Limitations of Garage Inspection

LIMITED INSPECTION, SNOW AND ICE COVER

The inspection of exterior features, such as walkways, driveways, decks, patios, roofs, and landscaping, was limited due to snow and ice cover. This restricted visibility and access to these areas, preventing a thorough evaluation of their condition. Recommend a follow-up inspection once snow and ice have melted to assess these features and identify any potential concerns.

Deficiency

4.9.1 Garage Structural

Material Defect

GARAGE, CONCRETE FOOTING, CRACKED WITH DISPLACEMENT

The concrete footing in the garage was observed to have cracking with visible displacement, indicating movement of the concrete rather than a superficial surface crack. This type of cracking is commonly associated with soil movement, settlement, frost-related heaving, or inadequate support beneath the footing. Displacement suggests the footing may no longer be performing as intended, which can affect the stability and load support of the garage structure above. While the full extent and progression of movement could not be determined at the time of inspection, this condition is more significant than typical shrinkage cracking and warrants attention. Recommend further evaluation by a qualified foundation contractor or structural professional to determine the cause of movement and to advise on appropriate repairs to prevent further deterioration or structural concerns.



Garage Back Right Corner

Recommendation

Contact a qualified professional.

4.11.1 Garage Roof Drainage System

Maintenance or Low Priority


DRAINAGE SYSTEM HEALTH

All downspouts should extend a minimum of 4-6' from the foundation or slab. Discharging near the foundation can affect the ability of the soil to support the weight of the structure above and can cause damage related to soil/foundation movement. Adding extensions can be a cheap way to avoid moisture issues in the future.

Also watch for downspouts that discharge along walkways or driveways. These areas can cause extra moisture to be pushed below the surface which can cause cracking and displacement. In Iowa our winters can also cause these discharge locations to freeze over and be a fall hazard.

Recommendation

Recommended DIY Project



5: ATTIC

		IN	LI	MA	MD	SC
5.1	General Overview and Limitations of Attic Inspection	X	X			
5.2	General Overview	X	X			
5.3	Roof Framing (from attic)	X	X			
5.4	Roof Sheathing (from Attic)	X	X			
5.5	Roof Structure Ventilation	X	X			
5.6	Attic Electrical	X	X			
5.7	Misc Attic Conditions (leakage, debris, etc.)	X	X			

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Attic Inspection:
Attic Inspected from:
 Attic not Inspected (stored items blocked hatch access)

General Overview and Limitations of Attic Inspection:
Insulation Type:
 Fiberglass Batt

General Overview and Limitations of Attic Inspection:
Roof Ventilation Type:
 Gable vents, No ventilation

General Overview and Limitations of Attic Inspection:
Location of Access:
 Half door

General Overview and Limitations of Attic Inspection:
Roof Framing Type:
 Unable to verify

General Overview and Limitations of Attic Inspection:
Average Insulation Depth:
 Less than 6 inches

General Overview and Limitations of Attic Inspection:
Roof Sheathing Material:
 Unable to verify

General Overview: Photo Documentation





Limitations

General Overview and Limitations of Attic Inspection

LIMITED INSPECTION, OCCUPANTS BELONGINGS BLOCKED ACCESS TO THE ATTIC

Access to the attic was blocked by the occupants' personal belongings, such as stored items or furniture, placed in or around the attic access hatch. This prevented a thorough inspection of the attic space, including insulation, framing, and ventilation. Clearing the area to allow safe access and scheduling a re-inspection is recommended to evaluate the attic's condition fully.



General Overview and Limitations of Attic Inspection

LIMITED INSPECTION, VAULTED CEILING

The attic inspection was limited due to the presence of a vaulted ceiling, which does not provide a standard attic space for access or evaluation. This restricted our ability to inspect areas such as insulation, ventilation, and roof framing. No assessment was made of areas that were not visually accessible. It is recommended to consult a professional if there are specific concerns related to the vaulted ceiling or the roof assembly.

6: KITCHEN

		IN	LI	MA	MD	SC
6.1	General Overview and Limitations of Kitchen Inspection	X	X			
6.2	Kitchen Electrical	X	X			
6.3	Cabinets	X	X			
6.4	Kitchen Plumbing / Sink	X	X	X		
6.5	Garbage Disposal					
6.6	Dishwasher					
6.7	Range	X				X
6.8	Range Hood or Built in Microwave	X		X		
6.9	Refrigerator	X	X			

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Kitchen Inspection: Floor Covering Materials

Sheet Vinyl

General Overview and Limitations of Kitchen Inspection: Stove Hook Ups

Electric

General Overview and Limitations of Kitchen Inspection: Walls and Ceilings

Drywall

Kitchen Plumbing / Sink: Video Documentation

General Overview and Limitations of Kitchen Inspection: Exhaust Type

No exhaust

Refrigerator: Photo documentation



Kitchen Plumbing / Sink: Photo documentation



Range: Photo documentation



Limitations

General Overview and Limitations of Kitchen Inspection

LIMITED INSPECTION, OCCUPANT BELONGINGS

The property was occupied at the time of inspection, and personal belongings, furniture, or stored items limited access to certain areas. As a result, a full visual inspection of all components and systems in these areas was not possible. Gold Shield Inspections cannot be held liable for any defects or issues that may exist in these inaccessible areas. We recommend a thorough review of these areas once they are cleared of belongings.

Deficiency

6.4.1 Kitchen Plumbing / Sink

KITCHEN SINK, OUTDATED S-TRAP



Maintenance or Low Priority

An S-trap configuration was observed beneath the sink. S-traps are plumbing traps that create an "S" shape in the drainpipe. While this design may effectively hold water to block sewer gases temporarily, it is prone to siphoning. This occurs when water in the trap is drawn out during drainage, leaving the trap dry and allowing sewer gases to enter the home.


The potential for sewer gases to enter the living space presents health and safety concerns due to unpleasant odors and possible exposure to harmful substances.

It is recommended to have the S-trap replaced with a properly installed P-trap, which is less prone to siphoning and more effective in maintaining a water seal. A licensed plumber should be consulted to evaluate the installation and ensure compliance with modern plumbing standards.

Recommendation

Contact a qualified plumbing contractor.

S-Trap vs. P-Trap



1st Floor Kitchen Sink



6.7.1 Range

 Safety Concern
KITCHEN STOVE, ANTI-TIP NOT INSTALLED

Anti-tip brackets are metal devices designed to prevent freestanding ranges from tipping. They are normally attached to a rear leg of the range or screwed into the wall behind the range, and are included in all installation kits. A unit that is not equipped with these devices may tip over if enough weight is applied to its open door, such as that from a large Thanksgiving turkey, or even a small child. A falling range can crush, scald, or burn anyone caught beneath.

Recommendation

Contact a qualified appliance repair professional.



1st Floor Kitchen Range

6.8.1 Range Hood or Built in Microwave

 Maintenance or Low Priority
NO EXHAUST SYSTEM INSTALLED

1ST FLOOR KITCHEN

No range hood or exhaust system was installed at the time of the inspection. The Inspector recommends that a range hood or air filtration system be installed to prevent possible moisture damage and grease accumulation on walls and ceiling adjacent to the range.

Recommendation

Contact a qualified professional.

7: BATHROOMS

		IN	LI	MA	MD	SC
7.1	General Overview and Limitations of Bathroom Inspection	X	X			
7.2	Bathroom Ventilation	X		X		
7.3	Bathroom Electrical	X	X			
7.4	Bathroom Sink	X	X	X		
7.5	Bathroom Toilet	X				
7.6	Bathroom Tub/Shower	X				

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Bathroom

Inspection: Bathroom Cabinets:
Veneer on MDF

General Overview and Limitations of Bathroom

Inspection: Bathroom Toilet
Type:
Low-volume flush (1.6 gal. [6 litres] or less)

General Overview and Limitations of Bathroom

Inspection: Bathroom Exhaust:
Fan with light


General Overview and Limitations of Bathroom

Inspection: Bathroom Floor:
Linoleum

General Overview and Limitations of Bathroom

Inspection: Bathroom Bathtub:
Cast iron

Bathroom Sink: Video Documentation



General Overview and Limitations of Bathroom

Inspection: Bathroom Sink:
Sink in a cabinet


General Overview and Limitations of Bathroom

Inspection: Bathroom Shower:
Antique curtain enclosure

Bathroom Toilet: Photo Documentation



Bathroom Tub/Shower: Photo Documentation



Bathroom Sink: Photo Documentation



Limitations

General Overview and Limitations of Bathroom Inspection

LIMITED INSPECTION, OCCUPANTS BELONGINGS

INTERIOR ROOMS

The property was occupied at the time of inspection, and personal belongings, furniture, or stored items limited access to certain areas. As a result, a full visual inspection of all components and systems in these areas was not possible. Gold Shield Inspections cannot be held liable for any defects or issues that may exist in these inaccessible areas. We recommend a thorough review of these areas once they are cleared of belongings.

Deficiency

7.2.1 Bathroom Ventilation

 Maintenance or Low Priority

BATHROOM VENTILATION, DIRTY OR CLOGGED EXHAUST COVER

The exhaust fan cover was dirty or clogged with dust, restricting airflow and reducing the fan's efficiency. Recommend cleaning the vent cover and inspecting the fan for further maintenance needs.

Recommendation

Recommended DIY Project



1st Floor Hall Bathroom Vent

7.4.1 Bathroom Sink

 Maintenance or Low Priority

BATHROOM SINK, INSUFFICIENT WATER FLOW

The sink exhibited low water pressure or insufficient flow, which may be caused by a clogged aerator, mineral deposits, or a plumbing issue. Recommend cleaning the aerator or consulting a plumber for further evaluation.

Recommendation

Contact a qualified plumbing contractor.



1st Floor Hall Bathroom Sink Cold Water Significantly Lower Water Pressure Compared To Hot Water

8: INTERIOR

		IN	LI	MA	MD	SC
8.1	General Overview and Limitations of Interior Inspection	X	X			
8.2	Thermostat	X				
8.3	Interior Floors	X	X			
8.4	Interior Ceilings and Walls	X	X			
8.5	Interior Doors	X				
8.6	Interior Stairs	X				
8.7	Interior Windows	X	X			
8.8	Interior Electrical	X	X			X
8.9	Doorbells/Detectors/Fans	X				X
8.10	Laundry Room	X	X	X		

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Interior Inspection: Floor Covering Materials

Sheet Vinyl, Wood

General Overview and Limitations of Interior Inspection: Window Glazing

Double-pane

General Overview and Limitations of Interior Inspection: # of Bedrooms

3

General Overview and Limitations of Interior Inspection: Interior Doors

Solid Wood

General Overview and Limitations of Interior Inspection: Window Material

Vinyl

General Overview and Limitations of Interior Inspection: # of Bathrooms

1

General Overview and Limitations of Interior Inspection: Walls and Ceilings

Drywall, Lath and Plaster

General Overview and Limitations of Interior Inspection: Window Operation

Double-hung, Casement

Thermostat: Photo Documentation



General Overview and Limitations of Interior Inspection: Air Quality

Gold Shield Inspections recommends Air Sampling for all residential properties. A home inspection is a visual inspection of the condition of your property. To ensure the air quality and ensure no hidden issues with toxins that can be produced by hidden mold inside walls, ductwork and structural components. We offer air sampling and quick turn around on all samples. Let us know if you would like more information.

Interior Floors: Interior Introduction

Inspection of the property interior does not include testing for mold, radon, asbestos, lead paint, or other environmental hazards unless specifically requested as an ancillary inspection. Inspection of the property interior typically includes:

- interior wall, floor and ceiling coverings and surfaces;
- doors and windows: condition, hardware, and operation;
- interior trim: baseboard, casing, molding, etc.;
- permanently-installed furniture, countertops, shelving, and cabinets; and
- ceiling and whole-house fans.

Laundry Room: Washer/Dryer Hook-up Photo

Washer and dryer hookups location.



Limitations

General Overview and Limitations of Interior Inspection

LIMITED INSPECTION, OCCUPANTS BELONGINGS

INTERIOR ROOMS

The property was occupied at the time of inspection, and personal belongings, furniture, or stored items limited access to certain areas. As a result, a full visual inspection of all components and systems in these areas was not possible. Gold Shield Inspections cannot be held liable for any defects or issues that may exist in these inaccessible areas. We recommend a thorough review of these areas once they are cleared of belongings. Due to the possibility of owners personal documentation we are unable to offer our 360 degree images of each room.

Deficiency

8.8.1 Interior Electrical

INTERIOR WIRING, MISSING JUNCTION BOX COVER

 Safety Concern

The junction box is missing its cover, leaving electrical wires exposed. This condition poses a safety hazard as it increases the risk of accidental contact, electrical shocks, and potential arcing, which can lead to fire hazards. Junction box covers are essential for containing wiring connections and preventing dust, debris, or unintended contact with live electrical components. Recommend installing a proper cover on the junction box to enhance safety and ensure compliance with electrical safety standards. A qualified electrician should address this issue promptly.

Recommendation

Contact a qualified electrical contractor.



Basement

8.9.1 Doorbells/Detectors/Fans

SMOKE DETECTOR INSTALL MORE**NFPA Information**

The Inspector recommends installing a smoke detector to provide improved fire protection for common areas. Generally-accepted current safety standards recommend smoke detectors be installed in the following locations:

1. In the immediate vicinity of the bedrooms
2. In all bedrooms
3. In each story of a dwelling unit, including basements and cellars, but not including crawl spaces and uninhabitable attics.
4. In units of 1,200 square feet or more, automatic fire detectors, in the form of smoke detectors shall be provided for each 1,200 square feet of area or part thereof. Any smoke detector located within 20 feet of a kitchen or bathroom containing a tub or shower must be a photoelectric type. The 1996 edition of the National Fire Protection Association (NFPA) 72 gives further guidance on the placement of smoke detectors, when required. Here are some examples from Chapter 2 of NFPA 72:
 5. Smoke detectors in a bedroom with a ceiling sloped greater than one foot in eight feet horizontally should be located on the high side of the ceiling.
 6. Smoke detectors should not be located within three (3) feet of a door to a bathroom containing a tub or a shower or the supply registers of a forced air HVAC system. Smoke detectors can be located on the ceiling with the side of the detector greater than four (4) inches from the wall or on the wall of a bedroom with the top of the detector located four (4) to twelve (12) inches down from the ceiling. All smoke detectors should be installed in accordance with the manufacturer's recommendation and be UL listed.

Recommendation

Recommended DIY Project



8.9.2 Doorbells/Detectors/Fans

CO DETECTOR NEEDED**NFPA Information**

The Inspector recommends installing a carbon monoxide detector. Carbon monoxide is an odorless, colorless, tasteless, toxic gas that is a product of the combustion process. Combustion appliances such as gas furnaces and heaters can introduce dangerously high levels of carbon monoxide onto the indoor air if combustion components need adjustment. Carbon monoxide detectors monitor indoor air and sound an alarm if dangerously high levels of carbon monoxide are detected. They are inexpensive and available at most hardware and home improvement stores. The Inspector recommends installation by a qualified contractor.

Recommendation

Recommended DIY Project



8.10.1 Laundry Room

LAUNDRY ROOM, WASHER DRAINS TO FLOOR DRAIN

 Maintenance or Low Priority

The washer was observed to drain directly into a floor drain. While this setup may be common in older homes, it can result in water backups if the drain becomes clogged or overwhelmed. Additionally, the absence of an air gap may lead to potential siphoning issues. Recommend ensuring the floor drain is clear and functional and consulting a plumber for recommendations on improving the drainage system if needed.

Recommendation

Contact a qualified plumbing contractor.



Basement

8.10.2 Laundry Room

LAUNDRY ROOM WASHER SUPPLY VALVE CORRODED

 Maintenance or Low Priority

The washer water supply valve in the laundry room shows visible corrosion on the valve body and/or connection points. Corrosion can develop from slow leaks, high moisture levels, or chemical reactions within the plumbing materials and may eventually lead to restricted water flow or leakage. If left unaddressed, this condition can worsen and cause water damage to surrounding areas or failure of the valve assembly. Recommend having a licensed plumber evaluate the corroded valve and replace it as needed to ensure proper operation and prevent potential leakage.

Recommendation

Contact a qualified professional.



Basement

9: PLUMBING

		IN	LI	MA	MD	SC
9.1	General Overview and Limitations of Plumbing Inspection	X	X			
9.2	Water Supply and Distribution	X	X	X		
9.3	Sewage and DWV Systems	X	X	X		
9.4	Visible Gas Piping System	X	X			
9.5	Water Heater	X	X			
9.6	Sump Pump					
9.7	Water Softener					
9.8	Radon Mitigation	X				

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Plumbing

Inspection: Sewage System Type:
Public

General Overview and Limitations of Plumbing

Inspection: Drain Waste and Vent Pipe Materials:
Cast Iron

General Overview and Limitations of Plumbing

Inspection: Water Supply Pipe:
Galvanized Steel, 1/2-inch

General Overview and Limitations of Plumbing

Inspection: Water Distribution Pipes:

1/2 and 3/4-inch galvanized steel,
1/2-inch and 3/4-inch copper,
Cross-linked Polyethylene (PEX)



General Overview and Limitations of Plumbing

Inspection: Water main shut off

General Overview and Limitations of Plumbing

Inspection: Water Temperature At Faucet

111.6



General Overview and Limitations of Plumbing

Inspection: Sump Pump:
No Sump pump installed

Water Heater: Water Heater Fuel Type

Electricity

Water Heater: Water Heater Manufacturer

A O Smith

Water Heater: Water Heater Manufacturer Date

2017

Water Heater: Water Heater Tank Capacity

40 gallons

Water Heater: Photo documentation



Radon Mitigation: Overview: Active Radon Mitigation System for Crawlspace, Basements, and Slab Homes

What is an Active Radon Mitigation System?

An active radon mitigation system is designed to reduce radon gas levels in homes, including those with crawlspaces, basements, or slab foundations. Radon is a naturally occurring radioactive gas linked to health risks like lung cancer. The system uses a fan to draw radon gas from beneath the home and vent it safely outdoors.

Key Components of an Active Radon Mitigation System

1.

Radon Suction Points:

- Basement: A hole is cored through the slab to access the soil beneath, where radon gas is collected and vented.
- Crawlspace: A sealed vapor barrier is installed over the exposed soil, with a suction point beneath to extract radon gas.
- Slab Home: Similar to a basement system, a suction point is installed by drilling into the slab to reach the sub-slab soil.

2.

Ventilation Piping:

PVC piping routes radon gas from the suction point(s) to above the roofline for safe outdoor discharge.

3.

Radon Fan:

An inline fan creates a vacuum to continuously draw radon gas from beneath the home and vent it outside. The fan is typically installed outside the living space, such as in an attic or exterior location.

4.

System Monitor:

A pressure gauge (manometer) on the vent pipe allows homeowners to verify the system is functioning properly.

How It Works:

- Crawlspace: The radon fan pulls gas from under the sealed vapor barrier, keeping radon from entering the home.
- Basements and Slabs: The fan draws radon from beneath the slab and vents it outdoors, maintaining a lower pressure under the slab to prevent radon infiltration.

Maintenance Tips:

1. Monitor System Performance: Regularly check the manometer or monitoring device to confirm the system is working.
2. Inspect Vapor Barriers (Crawlspaces): Ensure the barrier is intact with no tears or gaps.
3. Test Radon Levels Periodically: Retest radon levels every 2–3 years to ensure the system is maintaining safe levels.
4. Radon Fan Replacement: Fans typically last 5–10 years and should be replaced as needed.

Why It's Important:

An active radon mitigation system reduces radon levels to safer levels (below 4.0 pCi/L, as recommended by the EPA), protecting occupants from potential health risks. Regular monitoring and maintenance ensure continued system effectiveness.



Limitations

General Overview and Limitations of Plumbing Inspection

LIMITED INSPECTION, OCCUPANT BELONGINGS

The property was occupied at the time of inspection, and personal belongings, furniture, or stored items limited access to certain areas. As a result, a full visual inspection of all components and systems in these areas was not possible. Gold Shield Inspections cannot be held liable for any defects or issues that may exist in these inaccessible areas. We recommend a thorough review of these areas once they are cleared of belongings.

General Overview and Limitations of Plumbing Inspection

LIMITED INSPECTION, FINISHED AREAS

The inspection of plumbing items, included behind walls, ceilings, and floors, was limited due to the presence of finished surfaces such as drywall, paneling, or flooring materials. These finishes restrict access to the underlying plumbing elements, making it impossible to assess their condition fully. This limitation prevents a thorough evaluation of potential issues.

Water Heater

LIMITED INSPECTION, RESTRICTED ACCESS TO WATER HEATER

The water heater was not fully inspected due to limited accessibility. Obstructions or confined placement prevented a thorough evaluation of the unit's components, including the burner assembly, tank, and connections. Recommend clearing obstructions and scheduling a follow-up inspection to ensure the water heater is functioning properly and safely.

Water Softener

LIMITED INSPECTION DUE TO WATER SOFTENER OUTSIDE SOP

The water softener was not inspected as its evaluation falls outside the scope of our inspection and the InterNACHI Standards of Practice. Functionality, maintenance status, and overall condition of the unit were not assessed. Recommend consulting a qualified water treatment specialist for a full evaluation of the water softener system.

Deficiency

9.2.1 Water Supply and Distribution



Maintenance or Low Priority

CORRODED PIPES

Signs of corrosion were noted on the supply lines, particularly at joints or fittings. Corrosion weakens the pipes and increases the risk of leaks or bursts. Recommend replacing corroded sections with durable materials, such as copper or PEX.

Recommendation

Contact a qualified plumbing contractor.



Basement



Basement

9.2.2 Water Supply and Distribution



Maintenance or Low Priority

OUTDATED GALVANIZED PIPES

Galvanized steel pipes were observed, which are prone to internal corrosion and reduced water flow over time. These pipes are more likely to fail compared to modern materials. Recommend evaluating the system and replacing outdated pipes with updated materials.

Example Photo:



Recommendation

Contact a qualified professional.

9.3.1 Sewage and DWV Systems

INTERIOR, PLUMBING, D-TRAPS INSTALLED

Maintenance or Low Priority



D-traps were observed at one or more plumbing fixtures. D-traps are considered an outdated plumbing configuration and are more prone to siphoning, which can allow sewer gases to enter the living space if the water seal is lost. This condition is commonly found in older homes or where plumbing modifications were made without updating the trap configuration. While the plumbing may appear functional at the time of inspection, D-traps do not provide the same level of protection as modern P-traps and can contribute to odor issues or potential health concerns. Recommend correction by a qualified plumber, typically by replacing D-traps with properly configured P-traps to improve performance and reduce the risk of sewer gas intrusion.

Recommendation

Contact a qualified professional.

In Basement For 1st Floor Bathroom
Tub

10: STRUCTURE

		IN	LI	MA	MD	SC
10.1	General Overview and Limitations of Structural Component Inspection	X	X			
10.2	Wall Structure	X	X			
10.3	Framed Floor Structure and supports	X	X			
10.4	Foundation	X	X	X		
10.5	Slab	X	X			
10.6	Crawlspace	X	X			

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Structural Component Inspection: Home Structural Design

Balloon Framing

General Overview and Limitations of Structural Component Inspection: Foundation Method/Materials

Mortared stone foundation walls

General Overview and Limitations of Structural Component Inspection: Exterior Wall Structures

Conventional 2x4 Wood Frame

General Overview and Limitations of Structural Component Inspection: Main Floor Structure

Wooden boards over wood joists

General Overview and Limitations of Structural Component Inspection: Foundation Configuration

Unfinished basement, Crawlspace

General Overview and Limitations of Structural Component Inspection: Main Floor Structure- Intermediate Support

Mortared Stone Wall, Wood beam girder, Steel Posts, Wood posts

General Overview and Limitations of Structural Component Inspection: Homeowner's Responsibility

One of the most common problems in a house is a wet basement or foundation. You should monitor the walls and floors for signs of water penetration, such as dampness, water stains, peeling paint, efflorescence, and rust on exposed metal parts. In a finished basement, look for rotted or warped wood paneling and doors, loose floor tiles, and mildew stains. It may come through the walls or cracks in the floor, or from backed-up floor drains, leaky plumbing lines, or a clogged air-conditioner condensate line.

Crawlspace: Photo Documentation



Limitations

General Overview and Limitations of Structural Component Inspection

LIMITED INSPECTION, STRUCTURAL COMPONENTS BEHIND FINISHED SURFACES

The inspection of structural components, including walls, ceilings, and floors, was limited due to the presence of finished surfaces such as drywall, paneling, or flooring materials. These finishes restrict access to the underlying structural elements, making it impossible to assess their condition fully. This limitation prevents a thorough evaluation of potential issues such as hidden framing damage, water intrusion, pest activity, or improper modifications.

While no visible signs of structural concerns were observed at the time of the inspection, it is important to note that hidden defects may exist behind these finished surfaces. If concerns arise in the future, or if renovations are planned that involve removing these finishes, further evaluation by a qualified professional is recommended to assess the condition of the concealed structural components.

General Overview and Limitations of Structural Component Inspection

LIMITED INSPECTION, OCCUPANT BELONGINGS

The property was occupied at the time of inspection, and personal belongings, furniture, or stored items limited access to certain areas. As a result, a full visual inspection of all components and systems in these areas was not possible. Gold Shield Inspections cannot be held liable for any defects or issues that may exist in these inaccessible areas. We recommend a thorough review of these areas once they are cleared of belongings.

Deficiency

10.4.1 Foundation



Maintenance or Low Priority

FOUNDATION, EXCESSIVE EFFLORESCENCE

Excessive efflorescence was observed on the foundation wall. Efflorescence appears as a white, powdery substance caused by moisture traveling through the wall and depositing salts on the surface. While it is typically not a structural issue, it indicates moisture infiltration, which can contribute to other problems such as weakening of mortar or concrete, potential biological growth, and long-term deterioration of the foundation.

Recommendations:

1. Identify and address the source of moisture causing the efflorescence. This may involve improving exterior drainage, repairing downspouts, or addressing leaks in the foundation.
2. Remove the efflorescence using a dry brush or mild cleaning solution. Avoid using excessive water during cleaning, as this can worsen the moisture problem.
3. Consider applying a waterproofing sealant or membrane to the interior or exterior of the foundation to prevent further moisture penetration.
4. Monitor the area for recurring moisture issues and take corrective actions as needed.

Consultation with a waterproofing or foundation specialist is recommended to assess the extent of moisture infiltration and determine appropriate long-term solutions.

Recommendation

Contact a qualified waterproofing contractor

10.4.2 Foundation



Maintenance or Low Priority

FOUNDATION MORTAR IMPROPER REPAIR MATERIALS

Observed areas of missing or deteriorated mortar joints had been improperly filled using materials such as caulking and spray foam. These materials are not suitable substitutes for mortar and fail to provide the necessary strength, bond, and durability to maintain the structural integrity and weather resistance of the masonry. Caulking and foam can degrade quickly when exposed to the elements, allow moisture intrusion, and compromise the load distribution between masonry units. Proper tuck-pointing should be performed using a compatible mortar mix designed for the masonry type. Recommend evaluation and repair by a qualified mason to ensure the longevity and stability of the affected areas.

Recommendation

Contact a qualified masonry professional.



11: ELECTRICAL

		IN	LI	MA	MD	SC
11.1	General Overview and Limitations of Electrical Component Inspection	X				
11.2	Service Panel Cabinet	X				
11.3	Service Grounding System	X				

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of Electrical Component Inspection: Location
Basement

General Overview and Limitations of Electrical Component Inspection: Service Disconnect Location:
At Service Panel

General Overview and Limitations of Electrical Component Inspection: Service Panel Ampacity:
100 amps

General Overview and Limitations of Electrical Component Inspection: Distribution Pipe Bonding:
Pipes were bonded

General Overview and Limitations of Electrical Component Inspection: Service Panel Type:
Load Center

General Overview and Limitations of Electrical Component Inspection: Service Panel Manufacturer:
Square D

General Overview and Limitations of Electrical Component Inspection: Electrical Service Conductors:
Overhead service

General Overview and Limitations of Electrical Component Inspection: Service Disconnect Type:
Breaker

General Overview and Limitations of Electrical Component Inspection: Type of Branch Wiring:
Vinyl-coated, Solid Copper, Stranded Copper

Service Panel Cabinet: Photo documentation





Service Panel Cabinet: Development of Power Needs in Residential Homes

The list below is intended to be no more than a rough rule of thumb covering the average unimproved electrical supply over the last century, and would cover the average 1,500- to 2,000-square-foot home.

- 1900s to 1930s: 30-amp supply
- 1930s to 1950s: 60-amp supply
- 1950s to 1970s: 100-amp supply
- 1970s to 1980s: 150-amp supply
- 1980s to 2000s: 200-amp supply

Obviously, larger and more expensive homes have always required more power than the norm, and it is not unusual now to see 400+-amp services in high-end homes.

Service Grounding System : Bonding of Components

The purpose of bonding is to ensure the electrical continuity of the fault current path, provide the capacity and ability to conduct safely any fault current likely to be imposed, and to aid in the operation of the over-current protection device.

The panel enclosures need to be bonded to the grounding system. But there is also a very long list of other components that need to be connected to ground, since they have the potential to become energized to electrical faults. These components include:

- interior water piping;
- water heaters;
- around water meters;
- gas lines;
- electrical enclosures;
- electrical raceways;
- electric outlets or junction boxes;
- CSST gas piping (manufacturer's compliance); and
- telephone and cable TV systems.

12: HVAC

		IN	LI	MA	MD	SC
12.1	General Overview and Limitations of HVAC Inspection	X				
12.2	Ductwork	X	X	X		
12.3	Central Air Conditioner	X				
12.4	Furnace	X				
12.5	Combustion Air	X				
12.6	Combustion Gas Vent (Chimney)					

IN = Inspected LI = Limited Inspection MA = Marginal MD = Material Defect SC = Safety Concern

Information

General Overview and Limitations of HVAC Inspection:

Air Filter Location:

Behind sliding panel at furnace

General Overview and Limitations of HVAC Inspection:

Air Filter Size

20x25x5

General Overview and Limitations of HVAC Inspection:

Cooling System Brand:

Lennox

General Overview and Limitations of HVAC Inspection:

Cooling System Date

2019

General Overview and Limitations of HVAC Inspection:

Heating System Brand:


American Standard

General Overview and Limitations of HVAC Inspection:

Heating System Date

2025

Furnace: HVAC running video



Combustion Air: Combustion Air, Condensing High-Efficiency Furnace

CONDENSATION IN A HIGH-EFFICIENCY FURNACE



High efficiency furnace

General Overview and Limitations of HVAC Inspection: Homeowner's Responsibility


Most HVAC (heating, ventilating and air-conditioning) systems in houses are relatively simple in design and operation. They consist of four components: controls, fuel supply, heating or cooling unit, and distribution system. The adequacy of heating and cooling is often quite subjective and depends upon occupant perceptions that are affected by the distribution of air, the location of return-air vents, air velocity, the sound of the system in operation, and similar characteristics.

We highly recommend yearly maintenance inspections on all HVAC equipment. This has the ability to extend the life of the equipment and ensure proper functionality. These inspections are very cost effective and should be part of your yearly maintenance plan. Contact a local HVAC company and set up your yearly inspection today.



General Overview and Limitations of HVAC Inspection: BTU's (British Thermal Unit)

In heating and cooling we use the term BTU which is the amount of heat required to raise the temperature of 1 pound of water by 1 degree fahrenheit.



Central Air Conditioner: Photo documentation



Central Air Conditioner: Recommended Yearly Maintenance

Yearly HVAC maintenance is key to efficiency, reliability, and longevity. Neglecting it can lead to higher energy costs, poor performance, and unexpected breakdowns.

Benefits of Regular Maintenance:

- Energy Efficiency: Clean filters, coils, and fans improve performance and lower utility bills.
- Longer Lifespan: Prevents excessive wear, reducing costly replacements.
- Better Air Quality: Replacing filters and cleaning components reduces allergens and pollutants.
- Fewer Breakdowns: Early detection of issues prevents major failures and emergency repairs.
- Warranty Protection: Many manufacturers require routine maintenance to keep warranties valid.
- Consistent Comfort: Ensures reliable heating and cooling year-round.
- Eco-Friendly: Efficient systems use less energy and reduce environmental impact.

What Maintenance Includes:

- Cleaning coils, filters, and ducts.
- Testing system performance and refrigerant levels.
- Lubricating moving parts and tightening connections.
- Clearing condensation drains to prevent water damage.

Recommendation:

Schedule HVAC maintenance annually—spring for cooling systems and fall for heating—to maximize performance and prevent costly repairs. Investing in routine service ensures comfort, efficiency, and long-term savings.

The below listed company has been proven to keep their technicians exceptionally trained as well as they hold all the needed insurance and bonding. We believe they provide a great service consistently to their clients in East Central Iowa.



319-208-2159

Furnace: Photo documentation



Furnace: Disclaim Heat Exchanger

The heat exchanger within the furnace was not disassembled, inspected, or pressure tested during this home inspection. A standard home inspection is a visual and functional evaluation and does not include invasive or technically exhaustive testing of HVAC components. Detecting defects such as cracks or holes in the heat exchanger requires specialized equipment and procedures, which are beyond the scope of this inspection.

Heat exchanger damage, if present, may pose safety risks, including the potential for carbon monoxide (CO) leakage. To mitigate these risks, it is recommended that:

- The heat exchanger be further evaluated by a licensed HVAC technician, especially if the furnace is older, has not been serviced recently, or exhibits signs of improper operation.
- Carbon monoxide detectors be installed in key areas of the home, such as near sleeping areas and on each level of the home, to monitor for CO and alert occupants to dangerous conditions.
- The furnace and HVAC system receive regular professional maintenance to ensure safe and efficient operation.

Taking these preventative measures helps to protect the safety and well-being of the home's occupants and ensures that the HVAC system operates as intended.

Furnace: Recommend Yearly Maintenance

Yearly HVAC maintenance is key to efficiency, reliability, and longevity. Neglecting it can lead to higher energy costs, poor performance, and unexpected breakdowns.

Benefits of Regular Maintenance:

- Energy Efficiency: Clean filters, coils, and fans improve performance and lower utility bills.
- Longer Lifespan: Prevents excessive wear, reducing costly replacements.
- Better Air Quality: Replacing filters and cleaning components reduces allergens and pollutants.
- Fewer Breakdowns: Early detection of issues prevents major failures and emergency repairs.
- Warranty Protection: Many manufacturers require routine maintenance to keep warranties valid.
- Consistent Comfort: Ensures reliable heating and cooling year-round.
- Eco-Friendly: Efficient systems use less energy and reduce environmental impact.

What Maintenance Includes:

- Cleaning coils, filters, and ducts.
- Testing system performance and refrigerant levels.
- Lubricating moving parts and tightening connections.
- Clearing condensation drains to prevent water damage.

Recommendation:

Schedule HVAC maintenance annually—spring for cooling systems and fall for heating—to maximize performance and prevent costly repairs. Investing in routine service ensures comfort, efficiency, and long-term savings.

The below listed company has been proven to keep their technicians exceptionally trained as well as they hold all the needed insurance and bonding. We believe they provide a great service consistently to their clients in East Central Iowa.



319-208-2159

Limitations

Ductwork

LIMITED INSPECTION, DUCTWORK

During a standard residential home inspection we observe all duct work that is visible. We are unable to fully inspect any ductwork that is behind finished ceilings, walls and floors. These areas are not accessible without specialized equipment and should be considered not inspected.

Deficiency

12.2.1 Ductwork



Maintenance or Low Priority

DUCTWORK, RECOMMEND CLEANING

Visible accumulation of dust, debris, or potential biological growth inside the ductwork was observed. Contaminated ductwork can negatively impact indoor air quality and may exacerbate respiratory conditions for occupants. Cleaning the ductwork by a certified HVAC professional is recommended to improve air quality and system hygiene. Additionally, installing or maintaining air filters can help reduce future contamination.

- pets
- occupants with allergies or asthma
- cigarette or cigar smoke
- water contamination or damage to the home or HVAC system
- home renovation or remodeling projects

Some occupants are more sensitive to these contaminants than others. Allergy and asthma sufferers, as well as young children and the elderly tend to be more susceptible to the types of poor indoor air quality that air duct cleaning can help address.

NADCA's rule of thumb for consumers is that if your air ducts look dirty, they probably are, and that dirty HVAC systems should be inspected by a reputable, certified HVAC professional. Below are some other reasons homeowners choose to have their air ducts cleaned.

Recommend that all new home owners contact a qualified HVAC duct cleaning service.

Recommendation

Contact a qualified professional.

STANDARDS OF PRACTICE

Inspection Details

Gold Shield Inspections follows InterNACHI Standards of Practice

Roof Systems

3.1. Roof

I. The inspector shall inspect from ground level or the eaves:

- A. the roof-covering materials;
- B. the gutters;
- C. the downspouts;
- D. the vents, flashing, skylights, chimney, and other roof penetrations; and
- E. the general structure of the roof from the readily accessible panels, doors or stairs.

II. The inspector shall describe:

- A. the type of roof-covering materials.

III. The inspector shall report as in need of correction:

- A. observed indications of active roof leaks.

IV. The inspector is not required to:

- A. walk on any roof surface.
- B. predict the service life expectancy.
- C. inspect underground downspout diverter drainage pipes.
- D. remove snow, ice, debris or other conditions that prohibit the observation of the roof surfaces.
- E. move insulation.
- F. inspect antennae, satellite dishes, lightning arresters, de-icing equipment, or similar attachments.
- G. walk on any roof areas that appear, in the inspectors opinion, to be unsafe.
- H. walk on any roof areas if doing so might, in the inspectors opinion, cause damage.
- I. perform a water test.
- J. warrant or certify the roof.
- K. confirm proper fastening or installation of any

roof-covering material.

Exterior

3.2. Exterior

I. The inspector shall inspect:

- A. the exterior wall-covering materials, flashing and trim;
- B. all exterior doors;
- C. adjacent walkways and driveways;
- D. stairs, steps, stoops, stairways and ramps;
- E. porches, patios, decks, balconies and carports;
- F. railings, guards and handrails;
- G. the eaves, soffits and fascia;
- H. a representative number of windows; and

I. vegetation, surface drainage, retaining walls and grading of the property, where they may adversely affect the structure due to moisture intrusion.

II. The inspector shall describe:

- A. the type of exterior wall-covering materials.

III. The inspector shall report as in need of correction:

- A. any improper spacing between intermediate balusters, spindles and rails.

IV. The inspector is not required to:

- A. inspect or operate screens, storm windows, shutters, awnings, fences, outbuildings, or exterior accent lighting.
- B. inspect items that are not visible or readily accessible from the ground, including window and door flashing.
- C. inspect or identify geological, geotechnical, hydrological or soil conditions.
- D. inspect recreational facilities or playground equipment.
- E. inspect seawalls, breakwalls or docks.
- F. inspect erosion-control or earth-stabilization measures.
- G. inspect for safety-type glass.
- H. inspect underground utilities.
- I. inspect underground items.
- J. inspect wells or springs.
- K. inspect solar, wind or geothermal systems.
- L. inspect swimming pools or spas.
- M. inspect wastewater treatment systems, septic systems or cesspools.
- N. inspect irrigation or sprinkler systems.
- O. inspect drainfields or dry wells.
- P. determine the integrity of multiple-pane window glazing or thermal window seals.

Garage

Gold Shield Inspections follows InterNACHI Standards of Practice

Attic

3.9. Attic, Insulation & Ventilation

I. The inspector shall inspect:

- A. insulation in unfinished spaces, including attics, crawlspaces and foundation areas;
- B. ventilation of unfinished spaces, including attics, crawlspaces and foundation areas; and
- C. mechanical exhaust systems in the kitchen, bathrooms and laundry area.

II. The inspector shall describe:

- A. the type of insulation observed; and

- B. the approximate average depth of insulation observed at the unfinished attic floor area or roof structure.
- III. The inspector shall report as in need of correction:
 - A. the general absence of insulation or ventilation in unfinished spaces.
- IV. The inspector is not required to:
 - A. enter the attic or any unfinished spaces that are not readily accessible, or where entry could cause damage or, in the inspector's opinion, pose a safety hazard.
 - B. move, touch or disturb insulation.
 - C. move, touch or disturb vapor retarders.
 - D. break or otherwise damage the surface finish or weather seal on or around access panels or covers.
 - E. identify the composition or R-value of insulation material.
 - F. activate thermostatically operated fans.
 - G. determine the types of materials used in insulation or wrapping of pipes, ducts, jackets, boilers or wiring.
 - H. determine the adequacy of ventilation.

Kitchen

[Gold Shield Inspections follows InterNACHI Standards of Practice](#)

Bathrooms

[Gold Shield Inspections follows InterNACHI Standards of Practice](#)

Interior

3.10. Doors, Windows & Interior

- I. The inspector shall inspect:
 - A. a representative number of doors and windows by opening and closing them;
 - B. floors, walls and ceilings;
 - C. stairs, steps, landings, stairways and ramps;
 - D. railings, guards and handrails; and
 - E. garage vehicle doors and the operation of garage vehicle door openers, using normal operating controls.
- II. The inspector shall describe:
 - A. a garage vehicle door as manually-operated or installed with a garage door opener.
- III. The inspector shall report as in need of correction:
 - A. improper spacing between intermediate balusters, spindles and rails for steps, stairways, guards and railings;
 - B. photo-electric safety sensors that did not operate properly; and
 - C. any window that was obviously fogged or displayed other evidence of broken seals.
- IV. The inspector is not required to:
 - A. inspect paint, wallpaper, window treatments or finish treatments.
 - B. inspect floor coverings or carpeting.
 - C. inspect central vacuum systems.
 - D. inspect for safety glazing.
 - E. inspect security systems or components.
 - F. evaluate the fastening of islands, countertops, cabinets, sink tops or fixtures.
 - G. move furniture, stored items, or any coverings, such as carpets or rugs, in order to inspect the concealed floor structure.
 - H. move suspended-ceiling tiles.
 - I. inspect or move any household appliances.
 - J. inspect or operate equipment housed in the

garage, except as otherwise noted.

K. verify or certify the proper operation of any pressure-activated auto-reverse or related safety feature of a garage door.

L. operate or evaluate any security bar release and opening mechanisms, whether interior or exterior, including their compliance with local, state or federal standards.

M. operate any system, appliance or component that requires the use of special keys, codes, combinations or devices.

N. operate or evaluate self-cleaning oven cycles, tilt guards/latches, or signal lights.

O. inspect microwave ovens or test leakage from microwave ovens.

P. operate or examine any sauna, steamgenerating equipment, kiln, toaster, ice maker, coffee maker, can opener, bread warmer, blender, instant hot-water dispenser, or other small, ancillary appliances or devices.

Q. inspect elevators.

R. inspect remote controls.

S. inspect appliances.

T. inspect items not permanently installed.

U. discover firewall compromises.

V. inspect pools, spas or fountains.

W. determine the adequacy of whirlpool or spa jets, water force, or bubble effects.

X. determine the structural integrity or leakage of pools or spas.

Plumbing

3.6. Plumbing

I. The inspector shall inspect:

A. the main water supply shut-off valve;

B. the main fuel supply shut-off valve;

C. the water heating equipment, including the energy source, venting connections, temperature/pressure-relief (TPR) valves, Watts 210 valves, and seismic bracing;

D. interior water supply, including all fixtures and faucets, by running the water;

E. all toilets for proper operation by flushing;

F. all sinks, tubs and showers for functional drainage;

G. the drain, waste and vent system; and

H. drainage sump pumps with accessible floats.

II. The inspector shall describe:

A. whether the water supply is public or private based upon observed evidence;

B. the location of the main water supply shut-off valve;

C. the location of the main fuel supply shut-off valve;

D. the location of any observed fuel-storage system; and

E. the capacity of the water heating equipment, if labeled.

III. The inspector shall report as in need of correction:

A. deficiencies in the water supply by viewing the functional flow in two fixtures operated simultaneously;

B. deficiencies in the installation of hot and cold water faucets;

C. mechanical drain stops that were missing or did not operate if installed in sinks, lavatories and tubs; and

D. toilets that were damaged, had loose connections to the floor, were leaking, or had tank components that did not operate.

IV. The inspector is not required to:

- A. light or ignite pilot flames.
- B. measure the capacity, temperature, age, life expectancy or adequacy of the water heater.
- C. inspect the interior of flues or chimneys, combustion air systems, water softener or filtering systems, well pumps or tanks, safety or shut-off valves, floor drains, lawn sprinkler systems, or fire sprinkler systems.
- D. determine the exact flow rate, volume, pressure, temperature or adequacy of the water supply.
- E. determine the water quality, potability or reliability of the water supply or source.
- F. open sealed plumbing access panels.
- G. inspect clothes washing machines or their connections.
- H. operate any valve.
- I. test shower pans, tub and shower surrounds or enclosures for leakage or functional overflow protection.
- J. evaluate the compliance with conservation, energy or building standards, or the proper design or sizing of any water, waste or venting components, fixtures or piping.
- K. determine the effectiveness of anti-siphon, backflow prevention or drain-stop devices.
- L. determine whether there are sufficient cleanouts for effective cleaning of drains.
- M. evaluate fuel storage tanks or supply systems.
- N. inspect wastewater treatment systems.
- O. inspect water treatment systems or water filters.
- P. inspect water storage tanks, pressure pumps, or bladder tanks.
- Q. evaluate wait time to obtain hot water at fixtures, or perform testing of any kind to water heater elements.
- R. evaluate or determine the adequacy of combustion air.
- S. test, operate, open or close: safety controls, manual stop valves, temperature/pressure-relief valves, control valves, or check valves.
- T. examine ancillary or auxiliary systems or components, such as, but not limited to, those related to solar water heating and hot water circulation.
- U. determine the existence or condition of polybutylene plumbing.
- V. inspect or test for gas or fuel leaks, or indications thereof.

Structure

3.3. Basement, Foundation, Crawlspace & Structure

- I. The inspector shall inspect:
 - A. the foundation;
 - B. the basement;
 - C. the crawlspace; and
 - D. structural components.
- II. The inspector shall describe:
 - A. the type of foundation; and
 - B. the location of the access to the under-floor space.
- III. The inspector shall report as in need of correction:
 - A. observed indications of wood in contact with or near soil;
 - B. observed indications of active water penetration;
 - C. observed indications of possible foundation movement, such as sheetrock cracks, brick cracks, out-of-square door frames, and unlevel floors; and
 - D. any observed cutting, notching and boring of framing members that may, in the inspector's opinion, present a structural or safety concern.

- IV. The inspector is not required to:
- A. enter any crawlspace that is not readily accessible, or where entry could cause damage or pose a hazard to him/herself.
 - B. move stored items or debris.
 - C. operate sump pumps with inaccessible floats.
 - D. identify the size, spacing, span or location or determine the adequacy of foundation bolting, bracing, joists, joist spans or support systems.
 - E. provide any engineering or architectural service.
 - F. report on the adequacy of any structural system or component.

Electrical

3.7. Electrical

- I. The inspector shall inspect:
- A. the service drop;
 - B. the overhead service conductors and attachment point;
 - C. the service head, gooseneck and drip loops;
 - D. the service mast, service conduit and raceway;
 - E. the electric meter and base;
 - F. service-entrance conductors;
 - G. the main service disconnect;
 - H. panelboards and over-current protection devices (circuit breakers and fuses);
 - I. service grounding and bonding;
 - J. a representative number of switches, lighting fixtures and receptacles, including receptacles observed and deemed to be arc-fault circuit interrupter (AFCI)-protected using the AFCI test button, where possible;
 - K. all ground-fault circuit interrupter receptacles and circuit breakers observed and deemed to be GFCIs using a GFCI tester, where possible; and
 - L. smoke and carbon-monoxide detectors.
- II. The inspector shall describe:
- A. the main service disconnect's amperage rating, if labeled; and
 - B. the type of wiring observed.
- III. The inspector shall report as in need of correction:
- A. deficiencies in the integrity of the serviceentrance conductors insulation, drip loop, and vertical clearances from grade and roofs;
 - B. any unused circuit-breaker panel opening that was not filled;
 - C. the presence of solid conductor aluminum branch-circuit wiring, if readily visible;
 - D. any tested receptacle in which power was not present, polarity was incorrect, the cover was not in place, the GFCI devices were not properly installed or did not operate properly, evidence of arcing or excessive heat, and where the receptacle was not grounded or was not secured to the wall; and
 - E. the absence of smoke detectors.
- IV. The inspector is not required to:
- A. insert any tool, probe or device into the main panelboard, sub-panels, distribution panelboards, or electrical fixtures.
 - B. operate electrical systems that are shut down.
 - C. remove panelboard cabinet covers or dead fronts.
 - D. operate or re-set over-current protection devices or overload devices.
 - E. operate or test smoke or carbon-monoxide detectors or alarms
 - F. inspect, operate or test any security, fire or alarms systems or components, or other warning or signaling systems.
 - G. measure or determine the amperage or voltage of the main service equipment, if not visibly

labeled.

H. inspect ancillary wiring or remote-control devices.

I. activate any electrical systems or branch circuits that are not energized.

J. inspect low-voltage systems, electrical de-icing tapes, swimming pool wiring, or any timecontrolled devices.

K. verify the service ground.

L. inspect private or emergency electrical supply sources, including, but not limited to: generators, windmills, photovoltaic solar collectors, or battery or electrical storage facility.

M. inspect spark or lightning arrestors.

N. inspect or test de-icing equipment.

O. conduct voltage-drop calculations.

P. determine the accuracy of labeling.

Q. inspect exterior lighting.

HVAC

3.4. Heating

I. The inspector shall inspect:

A. the heating system, using normal operating controls.

II. The inspector shall describe:

A. the location of the thermostat for the heating system;

B. the energy source; and

C. the heating method.

III. The inspector shall report as in need of correction:

A. any heating system that did not operate; and

B. if the heating system was deemed inaccessible.

IV. The inspector is not required to:

A. inspect or evaluate the interior of flues or chimneys, fire chambers, heat exchangers, combustion air systems, fresh-air intakes, humidifiers, dehumidifiers, electronic air filters, geothermal systems, or solar heating systems.

B. inspect fuel tanks or underground or concealed fuel supply systems.

C. determine the uniformity, temperature, flow, balance, distribution, size, capacity, BTU, or supply adequacy of the heating system.

D. light or ignite pilot flames.

E. activate heating, heat pump systems, or other heating systems when ambient temperatures or other circumstances are not conducive to safe operation or may damage the equipment.

F. override electronic thermostats.

G. evaluate fuel quality.

H. verify thermostat calibration, heat anticipation, or automatic setbacks, timers, programs or clocks.

3.5. Cooling

I. The inspector shall inspect:

A. the cooling system, using normal operating controls.

II. The inspector shall describe:

A. the location of the thermostat for the cooling system; and

B. the cooling method.

III. The inspector shall report as in need of correction:

A. any cooling system that did not operate; and

B. if the cooling system was deemed inaccessible.

IV. The inspector is not required to:

A. determine the uniformity, temperature, flow, balance, distribution, size, capacity, BTU, or supply adequacy of the cooling system.

B. inspect portable window units, through-wall units, or electronic air filters.

C. operate equipment or systems if the exterior temperature is below 65 Fahrenheit, or when

other circumstances are not conducive to safe operation or may damage the equipment.

D. inspect or determine thermostat calibration, cooling anticipation, or automatic setbacks or clocks.

E. examine electrical current, coolant fluids or gases, or coolant leakage.