


Your Inspection Report





PREPARED FOR:

SHANNON ENRIGHT

INSPECTION DATE:

Monday, May 26, 2025

PREPARED BY:

Michael Lugton









Lugton Home Inspections 1221 Simcoe Street, Suite 519 Oshawa, ON L1G 4X2 905 925 2530

mikelugton@msn.com



June 18, 2025

Dear Shannon Enright,

RE: Report No. 1333, v.4 79 Old Colony Drive Whitby, ON L1R 2A4

Please find attached a copy of the updated report. The report has been updated to reflect my "Re Inspection" findings upon my return to the property on June 16, 2025. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thank you very much for choosing us to perform your home inspection.

Sincerely,

Michael Lugton on behalf of Lugton Home Inspections

Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON May 26, 2025

SUMMARY ROOFING

EXTERIOR

STRUCTURE

ECTRICAL

HEATING

COOLING INSULATION

ON PLUMBING

INTERIOR

APPENDIX

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Priority Maintenance Items

Roofing

SLOPED ROOFING \ Asphalt shingles

Condition: • Aging

Location: Throughout Roof

Task: Remove old shingles and replace with new

Time: Less than 3 years





1. Shingles are aging

Tillingios are aging

Condition: • Patched

Some shingles have been replaced over time.

Implication(s): Chance of water damage to structure, finishes and contents

Location: Throughout Roof

Task: Replace old shingles with new

Time: Less than 3 years

79 Old Colony Drive, Whitby, ON May 26, 2025

SUMMARY ROO

ROOFING EXTERIOR

STRUCTURE

FCTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX







3. Patched

4. Patched

May 26, 2025

Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON SUMMARY ROOFING

EXTERIOR

STRUCTURE

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX



5. Patched

Interior

BASEMENT \ Wet basement - evidence

Condition: • Stains

Implication(s): Chance of water damage to structure, finishes and contents

Location: Left Side Rear Corner of Basement Task: Further evaluation by a Foundation Specialist

Time: Immediate

79 Old Colony Drive, Whitby, ON May 26, 2025

lugtonhomeinspections.ca

SUMMARY ROC

ROOFING EXTERIOR

STRUCTURE

ECTRICAL

HEATING


COOLING


INSULATION

PLUMBING

INTERIOR

APPENDIX





Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON SUMMARY

ROOFING **EXTERIOR** STRUCTURE

May 26, 2025

HEATING


COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX





6. Water Stains

This concludes the Summary section.

SUMMARY

May 26, 2025

Report No. 1333, v.4

lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON SUMMARY ROOFING

EXTERIOR

STRUCTURE

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

Home Improvement - ballpark costs

79 Old Colony Drive, Whitby, ON lugtonhomeinspections.ca May 26, 2025

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

PLUMBING

APPENDIX

Descriptions

Sloped roofing material:

• Asphalt shingles




7. Asphalt shingles



9. Asphalt shingles



8. Asphalt shingles



10. Asphalt shingles

79 Old Colony Drive, Whitby, ON May 26, 2025 lugtonhomeinspections.ca

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

PLUMBING

APPENDIX



11. Asphalt shingles



12. Asphalt shingles



13. Asphalt shingles



14. Asphalt shingles

May 26, 2025

STRUCTURE ELECTRICAL

Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON SUMMARY ROOFING

APPENDIX



15. Asphalt shingles

Sloped roof flashing material: • Metal

Observations and Recommendations


SLOPED ROOFING \ Asphalt shingles

1. Condition: • Aging **Location**: Throughout Roof

Task: Remove old shingles and replace with new

Time: Less than 3 years





2. Condition: • Patched Some shingles have been replaced over time.



17. Shingles are aging

SUMMARY ROOFING STRUCTURE ELECTRICAL

APPENDIX

Implication(s): Chance of water damage to structure, finishes and contents


May 26, 2025

Location: Throughout Roof

79 Old Colony Drive, Whitby, ON

Task: Replace old shingles with new

Time: Less than 3 years







18. Patched

19. Patched

lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON May 26, 2025 lugtonhomeinspections.ca

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

COOLING

INSULATION

PLUMBING

APPENDIX



20. Patched

Inspection Methods and Limitations

General: • The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Inspection performed: • With binoculars from the ground • Eye Stick Extension Pole used with attached camera.

Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON SUMMARY ROOFING

EXTERIOR

May 26, 2025 STRUCTURE ELECTRICAL

APPENDIX

Descriptions

Gutter & downspout material: • Aluminum Gutter & downspout type: • Eave mounted

Gutter & downspout discharge: • Below grade

Lot slope: • Flat

Wall surfaces and trim:

• Brick



21. Brick

Driveway:

Asphalt



22. Asphalt Driveway

79 Old Colony Drive, Whitby, ON SUMMARY

ROOFING EXTERIOR May 26, 2025 STRUCTURE ELECTRICAL

PLUMBING

lugtonhomeinspections.ca

APPENDIX

Walkway:

Interlocking brick



23. Interlocking brick walkway

Deck:

Wood



24. Wood Deck



25. Wood Deck

Porch:


• Composite

lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON May 26, 2025

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

APPENDIX




26. Composite Porch

Fence:

Wood



27. Wood Fence



28. Wood Fence

Garage:

• Attached Garage

Report No. 1333, v.4 lugtonhomeinspections.ca 79 Old Colony Drive, Whitby, ON

PLUMBING SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL

APPENDIX



29. Attached Garage

May 26, 2025

Garage vehicle door operator (opener):

• Present



30. Garage Door Opener

Observations and Recommendations

RECOMMENDATIONS \ Overview

3. Condition: • No exterior recommendations are offered as a result of this inspection.

EXTERIOR

APPENDIX

May 26, 2025

Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON SUMMARY ROOFING

EXTERIOR

STRUCTURE ELECTRICAL

INSULATION

Inspection Methods and Limitations

General: • The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

79 Old Colony Drive, Whitby, ON SUMMARY

ROOFING

STRUCTURE ELECTRICAL

May 26, 2025

lugtonhomeinspections.ca

APPENDIX

Descriptions

Configuration: • Basement


Foundation material: • Poured concrete

Floor construction: • Joists

Exterior wall construction: • Wood frame / Brick veneer

Roof and ceiling framing:

• Trusses





31. Trusses

· Plywood sheathing

32. Trusses



33. Plywood sheathing

lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON

May 26, 2025

APPENDIX

ROOFING

STRUCTURE ELECTRICAL

COOLING

INSULATION

PLUMBING

Observations and Recommendations

RECOMMENDATIONS \ Overview

4. Condition: • No structure recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

General: • The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Inspection limited/prevented by: • Ceiling, wall and floor coverings • Carpet/furnishings • Storage • New finishes/paint Insulation

Attic/roof space: • Inspected from access hatch

Percent of foundation not visible: • 90 %

Not included as part of a building inspection: • Visible mold evaluation is not included in the building inspection report • The footings supporting the house are typically not visible and cannot be inspected. Only a small part of the foundation can be seen and inspected from outside the home. Finished or concealed portions of the interior of the foundation cannot be inspected.

lugtonhomeinspections.ca May 26, 2025

SUMMARY

ROOFING

79 Old Colony Drive, Whitby, ON

STRUCTURE ELECTRICAL

APPENDIX

Descriptions

Service entrance cable and location: • <u>Underground - cable material not visible</u>

Service size:

• 200 Amps (240 Volts)



34. 200 Amps

Main disconnect/service box rating: • 200 Amps

Main disconnect/service box type and location:

• Breakers - basement



35. Breakers



36. Breakers

ELECTRICAL

79 Old Colony Drive, Whitby, ON May 26, 2025

Report No. 1333, v.4

lugtonhomeinspections.ca

APPENDIX

ROOFING EXTERIOR

STRUCTURE ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

System grounding material and type: • Copper - water pipe

Distribution wire (conductor) material and type: • Copper - non-metallic sheathed

Type and number of outlets (receptacles): • Grounded - typical

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • GFCIs present

Smoke alarms (detectors): • Present

Carbon monoxide (CO) alarms (detectors): • Present

Observations and Recommendations

DISTRIBUTION SYSTEM \ Smoke alarms (detectors)

5. Condition: • Smoke Detectors *PLEASE SEE APPENDIX AT END OF REPORT*

Implication(s): Life Safety
Location: Throughout House

Task: Recommended that all Smoke Detectors are tested upon moving in to the house.

Time: Smoke detectors should be tested semi annually and replaced if required.

DISTRIBUTION SYSTEM \ Carbon monoxide (CO) alarms (detectors)

6. Condition: • Carbon Monoxide Detectors *PLEASE SEE APPENDIX AT END OF REPORT*

Implication(s): Life Safety
Location: Throughout House

Task: Recommended that all Carbon Monoxide Detectors are tested upon moving in to the house.

Time: Carbon Monoxide detectors should be tested semi annually and replaced if required.

Inspection Methods and Limitations

General: • The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

System ground: • Quality of ground not determined

79 Old Colony Drive, Whitby, ON SUMMARY

ROOFING

May 26, 2025 STRUCTURE ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

lugtonhomeinspections.ca

APPENDIX


Descriptions


Heating system type: • Furnace

Fuel/energy source: • Gas

Furnace manufacturer:

Rheem





38. Rheem

37. Rheem

Heat distribution: • Ducts and registers

Approximate capacity: • 70,000 BTU/hr

Efficiency: • High-efficiency

Exhaust venting method: • Direct vent - sealed combustion

Combustion air source: • Outside - sealed combustion

Approximate age: • 12 years

Main fuel shut off at: • Basement

Chimney/vent: • Abandoned

May 26, 2025

Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON

ROOFING

STRUCTURE ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

APPENDIX



39. Abandoned Chimney

Sidewall venting

Observations and Recommendations

RECOMMENDATIONS \ Overview

7. Condition: • No heating recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

General: • The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Safety devices: • Not tested as part of a building inspection

Heat loss calculations: • Not done as part of a building inspection

Heat exchanger: • Not accessible

COOLING & HEAT PUMP

79 Old Colony Drive, Whitby, ON May 26, 2025 Report No. 1333, v.4 lugtonhomeinspections.ca

APPENDIX

ROOFING

STRUCTURE ELECTRICAL

COOLING

INSULATION

PLUMBING

Descriptions

Air conditioning type: • Air cooled

Manufacturer: Kool King



40. Kool King



41. Kool King

Cooling capacity: • 30,000 BTU/hr

Compressor approximate age: • 12 years

Observations and Recommendations

RECOMMENDATIONS \ Overview

8. Condition: • No air conditioning or heat pump recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

General: • The cooling system cannot be tested when the outdoor temperature is below 65 Fahrenheit/18 Celsius.

Not part of a home inspection: • Home inspectors do not verify that the size of the indoor coil matches the outdoor coil

Report No. 1333, v.4

lugtonhomeinspections.ca

SUMMARY

APPENDIX

79 Old Colony Drive, Whitby, ON ROOFING

STRUCTURE ELECTRICAL

May 26, 2025

INSULATION

Descriptions

Attic/roof insulation material:

• Cellulose







43. Cellulose



44. Cellulose



45. Cellulose

Attic/roof insulation amount/value:

• <u>R-32</u>

79 Old Colony Drive, Whitby, ON May 26, 2025 Report No. 1333, v.4 lugtonhomeinspections.ca

SUMMARY


ROOFING

STRUCTURE ELECTRICAL

INSULATION

PLUMBING

APPENDIX




46. R-32

Attic/roof air/vapor barrier: • Plastic

Attic/roof ventilation:

• Roof and soffit vents







48. Roof vent

79 Old Colony Drive, Whitby, ON May 26, 2025 Report No. 1333, v.4 lugtonhomeinspections.ca

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

INSULATION

PLUMBING

APPENDIX





49. Roof vent

50. Roof vent



51. Roof vent

Observations and Recommendations

RECOMMENDATIONS \ Overview

9. Condition: • No insulation recommendations are offered as a result of this inspection.

79 Old Colony Drive, Whitby, ON May 26, 2025 Report No. 1333, v.4

lugtonhomeinspections.ca ROOFING STRUCTURE ELECTRICAL COOLING INSULATION PLUMBING

APPENDIX

Inspection Methods and Limitations

General: • Finding and identifying environmental issues such as asbestos is outside the scope of a home inspection. Asbestos may be present in many building products and materials. An Environmental Consultant can assist if this is a concern. Moisture problems may result in visible or concealed mould growth. An Environmental Consultant can assist if this is a concern.

General: • The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Attic inspection performed: • From access hatch

Roof ventilation system performance: • Not evaluated

Air/vapor barrier system: • Continuity not verified

Mechanical ventilation effectiveness: • Not verified

79 Old Colony Drive, Whitby, ON SUMMARY

ROOFING

STRUCTURE ELECTRICAL

May 26, 2025

PLUMBING

lugtonhomeinspections.ca

APPENDIX

Descriptions

General:

• Hot Tub



52. Hot Tub

Water supply source (based on observed evidence): • Public

Service piping into building: • Copper Supply piping in building: • Copper

Main water shut off valve at the:

Basement



53. Water Main Shutoff

lugtonhomeinspections.ca 79 Old Colony Drive, Whitby, ON May 26, 2025

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

PLUMBING

APPENDIX

Water flow and pressure: • Functional

Water heater type: • Induced draft

Water heater fuel/energy source: • Gas

Water heater manufacturer:

• GSW





Water heater tank capacity: • 50 gallons Water heater approximate age: • 11 years

Waste disposal system: • Public

Waste and vent piping in building: • Plastic

Water treatment system: Water Treatment Systems



55. GSW

79 Old Colony Drive, Whitby, ON May 26, 2025 lugtonhomeinspections.ca

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

PLUMBING

APPENDIX



56. Water Treatment

Main gas shut off valve location:

• Gas meter



57. Gas Meter

PLUMBING

Report No. 1333, v.4

lugtonhomeinspections.ca 79 Old Colony Drive, Whitby, ON May 26, 2025

ROOFING

STRUCTURE ELECTRICAL

COOLING

INSULATION

PLUMBING

APPENDIX

Observations and Recommendations

RECOMMENDATIONS \ Overview

10. Condition: • No plumbing recommendations are offered as a result of this inspection.

Inspection Methods and Limitations

General: • The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Items excluded from a building inspection: • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water heater relief valves are not tested • The performance of floor drains or clothes washing machine drains

79 Old Colony Drive, Whitby, ON May 26, 2025 SUMMARY

ROOFING STRUCTURE ELECTRICAL

INTERIOR

lugtonhomeinspections.ca

APPENDIX

Descriptions

Major floor finishes: • Carpet • Laminate • Ceramic • Vinyl

Major wall and ceiling finishes: • Plaster/drywall

Windows: • Sliders • Casement • Vinyl

Glazing: • Double

Exterior doors - type/material: • Sliding glass • Metal • Garage door - wood

Appliances: Refrigerator



58. Refrigerator

Dishwasher

79 Old Colony Drive, Whitby, ON May 26, 2025 Report No. 1333, v.4 lugtonhomeinspections.ca

SUMMARY

ROOFING

STRUCTURE ELECTRICAL

HEATING

COOLING

PLUMBING

INTERIOR

APPENDIX



59. Dishwasher

• Electric Range



60. Electric Range

Laundry facilities: • Washer • Dryer

May 26, 2025

Report No. 1333, v.4 lugtonhomeinspections.ca

SUMMARY ROO

ROOFING EXTERI

STRUCTURE

CTRICAL HE

ING

ING INSULATION

N PLUMBING

INTERIOR

APPENDIX

Kitchen ventilation: • Range hood

Bathroom ventilation: • Exhaust fan

79 Old Colony Drive, Whitby, ON

Laundry room ventilation: • Clothes dryer vented to exterior

Counters and cabinets: • Inspected
Stairs and railings: • Inspected

Observations and Recommendations


BASEMENT \ Wet basement - evidence

11. Condition: • Stains

Implication(s): Chance of water damage to structure, finishes and contents

Location: Left Side Rear Corner of Basement **Task**: Further evaluation by a Foundation Specialist

Time: Immediate



Report No. 1333, v.4

79 Old Colony Drive, Whitby, ON
SUMMARY ROOFING EXTERIOR


May 26, 2025


STRUCTURE

UMBING INTERIOR

lugtonhomeinspections.ca

SUMMARY APPENDIX





Report No. 1333, v.4

79 Old Colony Drive, Whitby, ON May 26, 2025

lugtonhomeinspections.ca

SUMMARY

ROOFING

FXTERIO

STRUCTURE

ELECTRIC/

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX



61. Water Stains

Inspection Methods and Limitations

General: • The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Not included as part of a building inspection: • Carbon monoxide alarms (detectors), security systems, central vacuum Central vacuum systems • Cosmetic issues • Appliances • Perimeter drainage tile around foundation, if any

END OF REPORT

May 26, 2025

Report No. 1333, v.4 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON ROOFING

STRUCTURE

INSULATION

COOLING

PLUMBING

APPENDIX



Canadian Association Of Home & Property **Inspectors**

2012 NATIONAL STANDARDS OF PRACTICE

The National Standards of Practice are a set of guidelines for home and property inspectors to follow in the performance of their inspections. They are the most widely accepted Canadian home inspection guidelines in use, and address all the home's major systems and components. The National Standards of Practice and Code of Ethics are recognized by many related professionals as the definitive Standards for professional performance in the industry.

These National Standards of Practice are being published to inform the public on the nature and scope of visual building inspections performed by home and property inspectors who are members of the Canadian Association of Home and Property Inspectors (CAHPI).

The purpose of the National Standards of Practice is to provide guidelines for home and property inspectors regarding both the inspection itself and the drafting of the inspection report, and to define certain terms relating to the performance of home inspections to ensure consistent interpretation.

To ensure better public protection, home and property inspectors who are members of CAHPI should strive to meet these Standards and abide by the appropriate provincial/regional CAHPI Code of Ethics.

These Standards take into account that a visual inspection of a building does not constitute an evaluation or a verification of compliance with building codes, Standards or regulations governing the construction industry or the health and safety industry, or Standards and regulations governing insurability.

Any terms not defined in these Standards shall have the meaning commonly assigned to it by the various trades and professions, according to context.

SUMMARY

ROOFING

EXTERIOR

RUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

INDEX

- 1. Introduction
- 2. Purpose and Scope
- 3. General Limitations and Exclusions
- 4. Structural Systems
- 5. Exterior Systems
- 6. Roof Systems
- 7. Plumbing Systems
- 8. Electrical Systems
- 9. Heating Systems
- 10. Fireplaces & Solid Fuel Burning Appliances
- 11. Air Conditioning Systems
- 12. Interior Systems
- 13. Insulation and Vapour Barriers
- 14. Mechanical and Natural Ventilation Systems

Glossary Note: Italicized words are defined in the Glossary.

1. INTRODUCTION

1.1 The Canadian Association of Home and Property Inspectors (CAHPI) is a not-for-profit association whose members include the following seven provincial/regional organizations: CAHPI-British Columbia., CAHPI-Alberta, CAHPI-Saskatchewan, CAHPI-Manitoba, OAHI (Ontario), AIBO (Quebec), and CAHPI-Atlantic. CAHPI strives to promote excellence within the profession and continual improvement of inspection services to the public.

2. PURPOSE AND SCOPE

2.1 The purpose of these National Standards of Practice is to establish professional and uniform Standards for private, fee-paid home inspectors who are members of one of the provincial/regional organizations of CAHPI. Home Inspections performed to these National Standards of Practice are intended to provide information regarding the condition of the systems and components of the building as inspected at the time of the Home Inspection. This does NOT include building code inspections.

These National Standards of Practice enable the building being inspected to be compared with a building that was constructed in accordance with the generally accepted practices at the time of construction, and which has been adequately maintained such that there is no significant loss of functionality.

It follows that the building may not be in compliance with current building codes, standards and regulations that are applicable at the time of inspection.

These National Standards of Practice apply to inspections of part or all of a building for the following building types:

- single-family dwelling, detached, semidetached or row house
- multi unit residential building
- residential building held in divided or undivided co ownership
- residential building occupied in part for a residential occupancy and in part for a commercial occupancy, as long as the latter use does not exceed 40% of the building's total area, excluding the basement.

2.2 THE INSPECTOR SHALL:

A. inspect:

 readily accessible, visually observable installed systems, and components of buildings listed in these National Standards of Practice.

B. report:

- 1. on those *systems* and *components* installed on the building inspected which, in the professional opinion or judgement of the *inspector*, *have a significant deficiency* or are unsafe or are near the end of their *service lives*.
- 2. a reason why, if not self-evident, the *system* or *component has a significant deficiency* or is unsafe or is near the end of its *service life*.
- the inspector's recommendations to correct or monitor the reported deficiency.
- 4. on any systems and components designated for inspection in these National Standards of Practice which were present at the time of the Home Inspection but were not inspected and a reason they were not inspected.
- **2.3** These National Standards of Practice are not intended to limit inspectors from:
 - **A.** including other inspection services in addition to those required by these National Standards of Practice provided the *inspector* is appropriately qualified and willing to do so.
 - **B.** excluding *systems* and *components* from the inspection if requested by the client or as dictated by circumstances at the time of the inspection.

3. GENERAL LIMITATIONS AND EXCLUSIONS

3.1 GENERAL LIMITATIONS:

- **A.** Inspections performed in accordance with these National Standards of Practice
- 1. are not technically exhaustive.
- will not identify concealed conditions or latent defects.

79 Old Colony Drive, Whitby, ON ROOFING

COOLING

INSULATION

PLUMBING

APPENDIX

3.2 GENERAL EXCLUSIONS:

- A. The inspector is not required to perform any action or make any determination unless specifically stated in these National Standards of Practice, except as may be required by lawful authority.
- **B.** *Inspectors* are NOT required to determine:
- 1. condition of systems or components which are not readily accessible.
- 2. remaining life of any system or component.
- 3. strength, adequacy, effectiveness, or efficiency of any system or component.
- 4. causes of any condition or deficiency.
- 5. methods, materials, or costs of corrections.
- 6. future conditions including, but not limited to, failure of systems and components.
- 7. suitability of the property for any use.
- 8. compliance with regulatory requirements (codes, regulations, laws, ordinances, etc.).
- 9. market value of the property or its marketability.
- 10.advisability of the purchase of the property.
- 11.presence of potentially hazardous plants, animals or insects including, but not limited to wood destroying organisms, diseases or organisms harmful to humans.
- 12.presence of any environmental hazards including, but not limited to toxins, carcinogens, noise, and contaminants in soil, water, and air.
- 13.effectiveness of any system installed or methods utilized to control or remove suspected hazardous substances.
- 14.operating costs of systems or components.
- 15.acoustical properties of any system or component
- 16.design adequacy with regards to location of the home, or the elements to which it is exposed.
- **C.** *Inspectors* are NOT required to offer or perform:
- 1. any act or service contrary to law, statute or regulation.
- 2. engineering, architectural and technical services.
- 3. work in any trade or any professional service other than home inspection.
- 4. warranties or guarantees of any kind.
- **D.** Inspectors are NOT required to operate:
- 1. any system or component which is shut down or otherwise inoperable.
- 2. any system or component which does not respond to normal operating controls.
- 3. shut-off valves.
- E. Inspectors are NOT required to enter:
- 1. any area which will, in the opinion of the inspector, likely be hazardous to the inspector or other persons or damage the property or its systems or components.

- 2. confined spaces.
- 3. spaces which are not readily accessible.
- **F.** *Inspectors* are NOT required to *inspect*:
- 1. underground items including, but not limited to storage tanks or other indications of their presence, whether abandoned or active.
- 2. systems or components which are not installed.
- 3. decorative items.
- 4. systems or components located in areas that are not readily accessible in accordance with these National Standards of Practice.
- detached structures.
- 6. common elements or common areas in multiunit housing, such as condominium properties or cooperative housing when inspecting an individual unit(s), including the roof and building envelope.
- 7. test and/or operate any installed fire alarm system, burglar alarm system, automatic sprinkler system or other fire protection equipment, electronic or automated installations, telephone, intercom, cable/internet systems and any lifting equipment, elevator, freight elevator, wheelchair lift, climbing chair, escalator or others;
- pools, spas and their associated safety devices, including fences.
- **G.** *Inspectors* are NOT required to:
- 1. perform any procedure or operation which will, in the opinion of the inspector, likely be hazardous to the *inspector* or other persons or damage the property or it's systems or components.
- 2. move suspended ceiling tiles, personal property, furniture, equipment, plants, soil, snow, ice, or debris.
- 3. dismantle any system or component, except as explicitly required by these National Standards of Practice.

79 Old Colony Drive, Whitby, ON ROOFING

COOLING

INSULATION

PLUMBING

APPENDIX

4. STRUCTURAL SYSTEMS

4.1 THE INSPECTOR SHALL:

A. inspect:

- 1. structural components including visible foundation and framing.
- 2. by *probing* a sample of structural components where deterioration is suspected or where clear indications of possible deterioration exist. Probing is NOT required when probing would damage any finished surface or where no deterioration is visible.

B. describe:

- 1. foundation(s).
- 2. floor structure(s).
- 3. wall structure(s).
- 4. ceiling structure(s).
- 5. roof structure(s).

C. report:

- 1. on conditions limiting access to structural components.
- 2. methods used to inspect the under-floor crawl
- 3. methods used to *inspect* the attic(s).

4.2 THE INSPECTOR IS NOT REQUIRED TO:

- A. provide any engineering service or architectural service.
- B. offer an opinion as to the adequacy of any structural system or component.

5. EXTERIOR SYSTEMS

5.1 THE INSPECTOR SHALL:

A. inspect:

- 1. exterior wall covering(s), flashing and trim.
- 2. all exterior doors.
- 3. attached or adjacent decks, balconies, steps, porches, and their associated railings.
- 4. eaves, soffits, and fascias where accessible from the ground level.
- 5. vegetation, grading, and surface drainage on the property when any of these are likely to adversely affect the building.
- 6. walkways, patios, and driveways leading to dwelling entrances.
- 7. landscaping structure attached or adjacent to the building when likely to adversely affect the building.
- 8. attached garage or carport.
- 9. garage doors and garage door operators for attached garages.

B. describe

1. exterior wall covering(s).

C. report:

1. the method(s) used to inspect the exterior wall elevations.

5.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. screening, shutters, awnings, and similar seasonal accessories.
- 2. fences.
- 3. geological, geotechnical or hydrological conditions.
- 4. recreational facilities.
- 5. detached garages and outbuildings.
- 6. seawalls, break-walls, dykes and docks.
- 7. erosion control and earth stabilization measures.

6. ROOF SYSTEMS

6.1 THE INSPECTOR SHALL:

A. inspect:

- 1. readily accessible roof coverings.
- 2. readily accessible roof drainage systems.
- 3. readily accessible flashings.
- 4. readily accessible skylights, chimneys, and roof penetrations.

B. describe

1. roof coverings.

C. report:

1. method(s) used to inspect the roof(s).

6.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. antennae and satellite dishes.
- 2. interiors of flues or chimneys.
- 3. other installed items attached to but not related to the roof system(s).

7. PLUMBING SYSTEMS

7.1 THE INSPECTOR SHALL:

A. inspect:

- 1. interior water supply and distribution systems including all fixtures and faucets.
- 2. drain, waste and vent systems including all
- 3. water heating equipment and associated venting systems.
- 4. water heating equipment fuel storage and fuel distribution systems.
- 5. fuel storage and fuel distribution systems.
- 6. drainage sumps, sump pumps, and related piping.

B. describe:

- 1. water supply, distribution, drain, waste, and vent piping materials.
- 2. water heating equipment including the energy source.
- 3. location of main water and main fuel shut-off valves.

May 26, 2025 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON

RY ROOFING

OFING EXTERIO

STRUCTUR

ELECTRICA

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

7.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. clothes washing machine connections.
- 2. wells, well pumps, or water storage related equipment.
- 3. water conditioning systems.
- 4. solar water heating systems.
- 5. fire and lawn sprinkler systems.
- 6. private waste disposal systems.

B. determine:

- 1. whether water supply and waste disposal *systems* are public or private.
- 2. the quantity or quality of the water supply.

C. operate:

1. safety valves or shut-off valves.

8. ELECTRICAL SYSTEMS

8.1 THE INSPECTOR SHALL:

A. inspect:

- 1. service drop.
- service entrance conductors, cables, and raceways.
- 3. service equipment and main disconnects.
- 4. service grounding.
- 5. interior components of service panels and sub panels.
- 6. distribution conductors.
- 7. overcurrent protection devices.
- 8. a *representative number* of *installed* lighting fixtures, switches, and receptacles.
- 9. ground fault circuit interrupters (GFCI) (if appropriate).
- 10.arc fault circuit interrupters (AFCI) (if appropriate).

B. describe:

- 1. amperage and voltage rating of the service.
- 2. location of main disconnect(s) and subpanel(s).
- 3. wiring methods.

C. report:

- presence of solid conductor aluminum branch circuit wiring.
- 2. absence of carbon monoxide detectors (if applicable).
- 3. absence of smoke detectors.
- 4. presence of ground fault circuit interrupters (GFCI).
- 5. presence of arc fault circuit interrupters (AFCI).

8.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- remote control devices unless the device is the only control device.
- 2. alarm systems and components.
- 3. low voltage wiring, systems and components.
- 4. ancillary wiring, *systems* and *components* not a part of the primary electrical power distribution *system*.

5. telecommunication equipment.

B. measure:

1. amperage, voltage, or impedance.

9. HEATING SYSTEMS

9.1 THE INSPECTOR SHALL:

A. inspect:

- readily accessible components of installed heating equipment.
- 2. vent systems, flues, and chimneys.
- 3. fuel storage and fuel distribution systems.

B. describe:

- 1. energy source(s).
- 2. heating method(s) by distinguishing characteristics.
- 3. chimney(s) and/or venting material(s).
- 4. combustion air sources.
- exhaust venting methods (naturally aspiring, induced draft, direct vent, direct vent sealed combustion).

9.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. interiors of flues or chimneys.
- 2. heat exchangers.
- 3. auxiliary equipment.
- 4. electronic air filters.
- 5. solar heating systems.

B. determine:

1. system adequacy or distribution balance.

10. FIREPLACES AND SOLID FUEL BURNING APPLIANCES

(Unless prohibited by the authority having jurisdiction)

10.1 THE INSPECTOR SHALL:

A. inspect:

- 1. system components
- 2. vent systems and chimneys

B. describe:

- 1. fireplaces and solid fuel burning appliances
- 2. chimneys

10.2 THE INSPECTOR IS NOT REQUIRED TO: A. inspect:

- 1. interior of flues or chimneys
- 2. screens, doors and dampers
- 3. seals and gaskets
- 4. automatic fuel feed devices
- 5. heat distribution assists whether fan assisted or gravity
- B. ignite or extinguish fires
- C. determine draught characteristics
- D. move fireplace inserts, stoves, or firebox contents

NATIONAL STANDARDS OF PRACTICE. © COPYRIGHT 2012 CANADIAN ASSOCIATION OF HOME & PROPERTY INSPECTORS. ALL RIGHTS RESERVED.

ON May 26, 2025 lugtonhomeinspections.ca

79 Old Colony Drive, Whitby, ON

SUMMARY ROOFING

OFING EXTER

STRUCTURE

ELECTRICA

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

11. AIR CONDITIONING SYSTEMS

11.1 THE INSPECTOR SHALL:

A. inspect

1. permanently *installed* central air conditioning equipment.

B. describe:

- 1. energy source.
- 2. cooling method by its distinguishing characteristics.

11.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect

- 1. electronic air filters.
- 2. portable air conditioner(s).

B. determine:

1. system adequacy or distribution balance.

12. INTERIOR SYSTEMS

12.1 THE INSPECTOR SHALL:

A. inspect:

- 1. walls, ceilings, and floors.
- 2. steps, stairways, and railings.
- 3. a representative number of countertops and installed cabinets.
- 4. a representative number of doors and windows.
- 5. walls, doors and ceilings separating the habitable spaces and the garage.

B. describe:

- 1. materials used for walls, ceilings and floors.
- 2. doors.
- 3. windows.

C. report

 absence or ineffectiveness of guards and handrails or other potential physical injury hazards.

12.2 THE INSPECTOR IS NOT REQUIRED TO:

A. inspect:

- 1. decorative finishes.
- 2. window treatments.
- 3. central vacuum systems.
- 4. household appliances.
- 5. recreational facilities.

13. INSULATION AND VAPOUR BARRIERS

13.1 THE INSPECTOR SHALL:

A. inspect:

insulation and vapour barriers in unfinished spaces.

B. describe:

1. type of insulation material(s) and *vapour* barriers in unfinished spaces.

C. report

- 1. absence of insulation in unfinished spaces within the building envelope.
- 2. presence of vermiculite insulation

13.2 THE INSPECTOR IS NOT REQUIRED TO:

A. disturb

- 1. insulation.
- 2. vapour barriers.

B. obtain sample(s) for analysis

1. insulation material(s).

14. MECHANICAL AND NATURAL VENTILATION SYSTEMS

14.1 THE INSPECTOR SHALL:

A. inspect:

- 1. ventilation of attics and foundation areas.
- 2. mechanical ventilation systems.
- ventilation systems in areas where moisture is generated such as kitchen, bathrooms, laundry rooms.

B. describe:

- 1. ventilation of attics and foundation areas.
- 2. mechanical ventilation systems.
- ventilation systems in areas where moisture is generated such as: kitchens, bathrooms and laundry rooms.

C. report:

 absence of ventilation in areas where moisture is generated such as: kitchens, bathrooms and laundry rooms.

14.2 THE INSPECTOR IS NOT REQUIRED TO:

- 1. determine indoor air quality.
- 2. determine system adequacy or distribution balance.

lugtonhomeinspections.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

GLOSSARY

Adjacent

Nearest in space or position; immediately adjoining without intervening space.

Alarm Systems

Warning devices, installed or free-standing, including but not limited to; carbon monoxide detectors, flue gas and other spillage detectors, security equipment, ejector pumps and smoke alarms.

Architectural Service

Any practice involving the art and science of building design for construction of any structure or grouping of structures and the use of space within and surrounding the structures or the design for construction, including but not specifically limited to, schematic design, design development, preparation of construction contract documents, and administration of the construction contract, adequacy of design for the location and exposure to the elements.

Automatic Safety Controls

Devices designed and installed to protect *systems* and *components* from unsafe conditions.

Component

A part of a system.

Confined Spaces

An enclosed or partially enclosed area that:

- 1. Is occupied by people only for the purpose of completing work.
- 2. Has restricted entry/exit points.
- 3. Could be hazardous to people entering due to:
- a. its design, construction, location or atmosphere.
- b. the materials or substances in it, or
- $\ensuremath{\mathbf{c}}.$ any other conditions which prevent normal inspection procedure.

Decorative

Ornamental; not required for the operation of the essential *systems* and *components* of a building.

Describe

To report a system or component by its type or other observed, significant characteristics to distinguish it from other systems or components.

Determine

To find out, or come to a conclusion by investigation.

Dismantle

To take apart or remove any component, device, or piece of equipment that would not be taken apart or removed by a homeowner in the course of normal and routine home owner maintenance.

Engineering Service

Any professional service or creative work requiring engineering education, training, and experience and the application of special knowledge of the mathematical, physical and engineering sciences to such professional service or creative work as consultation, investigation, evaluation, planning, design and supervision of construction for the purpose of assuring compliance with the specifications and design, in conjunction with structures, buildings, machines, equipment, works or processes.

Functionality

The purpose that something is designed or expected to fulfill

Further Evaluation

Examination and analysis by a qualified professional, tradesman or service technician beyond that provided by the *home inspection*.

Home Inspection

The process by which an *inspector* visually examines the *readily accessible systems* and *components* of a building and which *describes* those *systems* and *components* in accordance with these National Standards of Practice.

Household Appliances

Kitchen, laundry, and similar appliances, whether *installed* or freestanding.

Inspect

To examine readily accessible systems and components of a building in accordance with these National Standards of Practice, where applicable using normal operating controls and opening readily openable access panels.

Inspector

A person hired to examine any *system* or *component* of a building in accordance with these National Standards of Practice.

Installed

Set up or fixed in position for current use or service.

Monitor

Examine at regular intervals to detect evidence of change.

Normal Operating Controls

Devices such as thermostats, switches or valves intended to be operated by the homeowner.

Operate

To cause to function, turn on, to control the function of a machine, process, or system.

May 26, 2025

lugtonhomeinspections.ca

SUMMARY

79 Old Colony Drive, Whitby, ON ROOFING

COOLING

INSULATION

PLUMBING

APPENDIX

Probing

Examine by touch.

Readily Accessible

Available for visual inspection without requiring moving of personal property, dismantling, destructive measures, or any action which will likely involve risk to persons or property.

Readily Openable Access Panel

A panel provided for homeowner inspection and maintenance that is within normal reach, can be removed by one person, and is not sealed in place.

Recreational Facilities

Spas, saunas, steam baths, swimming pools, exercise, entertainment, athletic, playground or other similar equipment and associated accessories.

Report.

To communicate in writing.

Representative Number

One *component* per room for multiple similar interior components such as windows and electric outlets; one component on each side of the building for multiple similar exterior components.

Roof Drainage Systems

Components used to carry water off a roof and away from a building.

Sample

A representative portion selected for inspection.

Service Life/Lives

The period during which something continues to function fully as intended.

Significant Deficiency

A clearly definable hazard or a clearly definable potential for failure or is unsafe or not functioning.

Shut Down

A state in which a system or component cannot be operated by normal operating controls.

Solid Fuel Burning Appliances

A hearth and fire chamber or similar prepared place in which a fire may be built and which is built in conjunction with a chimney; or a listed assembly of a fire chamber, its chimney and related factory-made parts designed for unit assembly without requiring field construction.

Structural Component

A component that supports non-variable forces or weights (dead loads) and variable forces or weights (live loads).

System

A combination of interacting or interdependent components, assembled to carry out one or more functions.

Technically Exhaustive

An inspection is technically exhaustive when it is done by a specialist who may make extensive use of measurements, instruments, testing, calculations, and other means to develop scientific or engineering findings, conclusions, and recommendations.

Under-floor Crawl Space

The area within the confines of the foundation and between the ground and the underside of the floor.

Unsafe

A condition in a readily accessible, installed system or component which is judged to be a significant risk of personal injury during normal, day-to-day use. The risk may be due to damage, deterioration, missing or improper installation or a change in accepted residential construction Standards.

Vapour Barrier

Material used in the building envelope to retard the passage of water vapour or moisture.

Visually Accessible

Able to be viewed by reaching or entering.

Wiring Methods

Identification of electrical conductors or wires by their general type, such as "non-metallic sheathed cable" ("Romex"), "armored cable" ("bx") or "knob and tube",

Note - In these National Standards of Practice, redundancy in the description of the requirements, limitations and exclusions regarding the scope of the Home Inspection is provided for clarity not emphasis.

 $(\textit{CAHPI acknowledges The American Society of Home Inspectors}^{\circledcirc}, Inc.$ (ASHI®) for the use of their Standards of Practice (version January 1, 2000)

(AUGUST 22/12 VER. F)

lugtonhomeinspections.ca

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRIC

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX

INSTALL SMOKE ALARMS IT'S THE LAW!



Most fatal fires occur at night when people are asleep. Often, victims never wake up. A working smoke alarm will detect smoke and sound an alarm to alert you, giving you precious time to escape.

Every home in Ontario must have a working smoke alarm on every storey and outside all sleeping areas.

Homeowners

It is the responsibility of homeowners to install and maintain smoke alarms on every storey of their home and outside sleeping areas.

Landlords

It is the responsibility of landlords to ensure their rental properties comply with the law.

Tenants

If you are a tenant of a rental property and do not have the required number of smoke alarms, contact your landlord immediately. It is against the law for tenants to remove the batteries or tamper with the alarm in any way.

Failure to comply with the Fire Code smoke alarm requirements could result in a ticket for \$235 or a fine of up to \$50,000 for individuals or \$100,000 for corporations

SMOKE ALARM INSTALLATION AND MAINTENANCE

Choose the right alarms

There are smoke alarms available with different features and applications, so choosing the right alarm can be confusing. Some of the features to consider include:

- Power Source: Smoke alarms
 can be electrically powered, battery powered, or a combination of
 both. If you are installing an electrically powered alarm it is recommended that it have a battery
 back-up in case of power failures.
- Technology: most smoke alarms employ either ionization or photoelectric technology. Ionization alarms may respond slightly faster to flaming-type fires, while photoelectric alarms may be quicker at detecting slow, smouldering fires.
- Pause feature: Smoke alarms with a pause button are highly recommended as it permits the alarm to be temporarily silenced without disconnecting the power source.

Install in the proper locations

Smoke alarms must be installed on each storey of the home as well as outside sleeping areas. Because smoke rises, smoke alarms should be installed on the ceiling. If this is not possible, install the alarm high up on a wall. Always follow the

manufacturer's instructions when installing smoke alarms.

Avoid putting smoke alarms too close to bathrooms, windows, ceiling fans and heating and cooking appliances.

Test smoke alarms monthly

Test your smoke alarms every month by using the test button on the alarm. When the test button is pressed, the alarm should sound. If it fails to sound, make sure that the battery is installed correctly or install a new battery. If the alarm still fails to sound, replace the smoke alarm with a new one.

Change the batteries every year

Install a new battery at least once a year, or as recommended by the manufacturer. Install a new battery if the low-battery warning sounds or if the alarm fails to sound when tested.

Vacuum alarms annually

Dust can clog your smoke alarms. Battery-powered smoke alarms should be cleaned by opening the cover of the alarm and gently vacuuming the inside with a soft bristle brush.

For electrically-connected smoke alarms, first shut off the power to the unit, and then gently vacuum the outside vents of the alarm only. Turn the power back on and test the alarm.

Replace older smoke alarms

All smoke alarms wear out. If your alarms are more than 10 years old, replace them with new ones.

Handle nuisance alarms

Steam from the shower or cooking in the oven, stove or toaster can cause smoke alarms to activate. If these types of nuisance alarms occur, do not remove the battery. There are several options you can try to reduce nuisance alarms.

- Relocate the alarm. Sometimes moving the alarm just a few inches can make the difference.
- Install a smoke alarm with a pause button that will allow you to temporarily silence the alarm.
- Replace alarms located near kitchens with photo-electric types.

Plan your escape

Make sure that everyone knows the sound of the smoke alarm and what to do if it activates. Create an escape plan with the entire household and practice it. Make sure your plan identifies two ways out of each room, if possible, and a meeting place outside. Once outside, stay outside. Never re-enter a burning building. Call the fire department from a neighbours' home or cell phone.

Office of the Fire Marshal © 2006 www.ofm.gov.on.ca



FOR MORE INFORMATION ABOUT SMOKE ALARMS, CONTACT YOUR LOCAL FIRE DEPARTMENT

lugtonhomeinspections.ca

SUMMARY

ROOFING

FXTERIO

STRUCTURE

ELECTRIC

HEATIN

COOLING

INSULATION

PLUMBING

INTERIOR

APPENDIX



Often called the invisible killer, carbon monoxide is an invisible, odorless, colorless gas created when fuels (such as gasoline, wood, coal, natural gas, propane, oil, and methane) burn incompletely. In the home, heating and cooking equipment that burn fuel can be sources of carbon monoxide.

- O alarms should be installed in a central location outside each sleeping area and on every level of the home and in other locations where required by applicable laws, codes or standards. For the best protection, interconnect all CO alarms throughout the home. When one sounds, they all sound.
- Follow the manufacturer's instructions for placement and mounting height.
- Choose a CO alarm that is listed by a qualified testing laboratory.
- Call your local fire department's non-emergency number to find out what number to call if the CO alarm sounds.
- Test CO alarms at least once a month; replace them according to the manufacturer's instructions.
- If the audible trouble signal sounds, check for low batteries. If the battery is low, replace it. If it still sounds, call the fire department.
- If the CO alarm sounds, immediately move to a fresh air location outdoors or by an open window or door. Make sure everyone inside the home is accounted for. Call for help from a fresh air location and stay there until emergency personnel.
- If you need to warm a vehicle, remove it from the garage immediately after starting it. Do not run a vehicle or other fueled engine or motor indoors, even if garage doors are open. Make sure the exhaust pipe of a running vehicle is not covered with snow.
- During and after a snowstorm, make sure vents for the dryer, furnace, stove, and fireplace are clear of snow build-up.
- 3)) A generator should be used in a well-ventilated location outdoors away from windows, doors and vent openings.
-))) Gas or charcoal grills can produce CO only use outside.



Your Source for SAFETY Information

 $\textbf{NFPA} \ \mathsf{Public} \ \mathsf{Education} \ \mathsf{Division} \bullet \mathsf{1} \ \mathsf{Batterymarch} \ \mathsf{Park}, \mathsf{Quincy}, \mathsf{MA} \ \mathsf{02169}$

HOME HEATING EOUIPMENT



Have fuel-burning heating equipment and chimneys inspected by a professional every year before cold weather sets in. When using a fireplace, open the flue for adequate ventilation. Never use your oven to heat your home.

FACTS

- A person can be poisoned by a small amount of CO over a longer period of time or by a large amount of CO over a shorter amount of time.
- In 2010, U.S. fire departments responded to an estimated 80,100 non-fire CO incidents in which carbon monoxide was found, or an average of nine calls per hour.

www.nfpa.org/education @NFPA 2016