

## **Action Jackson Drain Cleaning & Plumbing**

Rick Nelson

(360) 708-7107

rickn@comcast.net

| AMOUNT DUE   | \$0.00       |  |  |  |
|--------------|--------------|--|--|--|
| DUE          | Net 30       |  |  |  |
| INVOICE DATE | Sep 10, 2024 |  |  |  |
| SERVICE DATE | Sep 09, 2024 |  |  |  |
| INVOICE      | #5738        |  |  |  |

**CONTACT US** 

7306 210th St SW Edmonds, WA 98026

(425) 877-5601

actionjacksondcap@yahoo.com

unit price

Service completed by:

## **INVOICE**

| Controcs   | 919  | ariit prioc   | arriount |
|--|--|---|----------|
| Sewer Scope  | 1.0  | \$275.00  | \$275.00 |
| 111 N 97th St, Seattle, WA 98103   |  |   |          |
| Technician accessed the line from pulled toilet in the downstairs bathroom. Line approximately 5' the line transitions to 4" pvc plastic. At approximately 7' the line approximately 30' the line transitions to 6" concrete. Line ties into the city main at appears to be fair condition but there are some very minor root intrusions beginning to line. Techs recommend scoping the line again in 2-3 years in order to check up on the growth of the roots. Tech believes there is a cleanout on the exterior of the home allowhen facing the front door, but it appears to either be under the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the paver stones or buried in the control of the control of the paver stones or buried in the control of | transitions to 4" opproximately 81'. I grow into the 6" phealth of the line along the porch on the stranger of | concrete. At The concrete portion of the as well as the |          |
| Thank you,<br>Jacob.   |  |   |          |
| Sewer Scope Legality   | 1.0  | \$0.00  | \$0.00   |
| Sewer Scope Legality - sewer inspection legality - Sewer inspections cannot be guarantis what we see at this time. Things in the line can change due to many reasons. Sewer any issues or problems that may arise in the future.   |  |   |          |
| USB Recording  | 1.0  | \$0.00  | \$0.00   |
| Pulled Toilet  | 1.0  | \$50.00   | \$50.00  |
| Fulled Tollet  |  |   |          |

Services subtotal: \$334.63

| Subtotal    |           |             |             | \$334.63  |
|-------------|-----------|-------------|-------------|-----------|
| Discount    |           |             |             | - \$50.00 |
| Total Tax   |           |             |             | \$0.00    |
| No Tax (0%) |           |             |             | \$0.00    |
| Total       |           |             |             | \$284.63  |
|             |           |             |             |           |
|             | Payment I | History     |             |           |
|             | Sep 09    | Mon 12:46pm | Credit Card | \$284.63  |

3.5% processing fee applicable if paying by CC. Please contact our office for more information.