

FOUNDATION INSPECTION



FOUNDATION INSPECTION

Mr. Joo B Lee
4300 Rose St.
Houston Texas 77007
Joo.b.lee2@gmail.com

12/04/2024

INSPECTION ADDRESS:
3052 Rain Dance Loop
Harker Heights Texas

FOUNDATION INSPECTION:

Contractor (Rocky Allen Owner/ Partner) Went to the above address and found the following: Upon inspection contractor found the home's foundation had not been maintained around the perimeter. Contractor strongly suggest gutters. As of today 12/04/2024, contractor found home to be stable and -2 inches throughout the home.

EVERYTHING LISTED IN THIS FOUNDATION INSPECTION IS RECOMMENDED BY CLAUDE ALLEN SPECILAIZED HOUSE LEVELING FOUNDATION REPAIR & CONCRETE LLC..

(FOUNDATION INSPECTION FEE) DUE: - \$375.00

Thank You!

Ashley P. [Signature]

CONTRACTOR
1130 FM 2271
BELTON TX 76513
(254)931-04335
ASHLEY@CLAUDEALLENHOUSELEVELING.COM

12/4/24
DATE

STATUS OF INSPECTION: **COMPLETED**

