

Home report

Powered by CUBICASA

3074 Sumter Valley Cir

Henderson

Highlights



1 Kitchen



2 Bedroom



3 Bath



1 Office



25 Doors



27 Windows

Nearby services

Data source: Google Maps



Strada, 1.2 mi



Jolly Mart, 0.8 mi



**DaVita Anthem Village
Dialysis, 1.6 mi**



Rio Secco Golf Club, 0.9 mi




**Romano Mercato Italiano,
0.8 mi**



**Henderson Executive
Airport, 1.4 mi**

Floor plan



Appendix 1: Data sheet

Bath - 3	Bath - Toilet - 1	Utility - 1
Utility - Laundry - 1	Hall - 2	Bedroom - 2
Bedroom - Master - 1	Garage - 1	Office - 1
Entry - 1	Kitchen - 1	