

6712 Panther Creek

Items Fixed After Pre-Inspection Report Performed on 8/6/2024

- Wired in doorbell
- Replaced missing smoke detectors – Installed wired smoke detectors
- Fixed toilet seat
- Replaced bottom part of the cabinet under sink
- Determined why the front door was hard to open – Fixed the issue with the front door
- Trimmed the trees
- Replaced broken window in upstairs bedroom