

TANK PUMPING REPORT

Site Name:

Location: 7353 CEDAR HOUSE
CLINTON
Tax ID: R32801-345-4300
Use:

Service Company:

Celtic Risers
PO Box 27
Clinton, WA 98236
360 341 2863

Serviced: 04/15/2025 by: Trevor Hein

Submitted 04/26/2025 by: Eamonn Roche

Dump Location: La Conner Waste Water Treatment Plant

Jurisdiction ID: R32801-345-4300

COMMENTS

This is a pumping report only. See inspection report for system component details.
Inlet side to the pump tank was uncovered to give better access for pumping. A riser was installed on this afterwards.

TANK: Septic Tank - 2 Compartment 1000 gallon concrete tank / effluent filter

Effluent level within operational limits (if NO explain in comments):	YES	
Total Gallons pumped from tank (Number only, no text):	1000	
Effluent returning back into tank after pumping:	NO	
Access Risers installed to grade (N/A if not present):	YES	
Tank Condition Good:	YES	
Baffles in good condition (N/A if not present):		
Effluent screen cleaned (N/A if not present):		
Effluent surfacing around site components (N/A if not checked):		
Were repairs made to the Tank or Tank Components? (if YES explain in comments):	NO	

TANK: Pump Tank 1000 gallon concrete tank

Effluent level within operational limits (if NO explain in comments):	YES	
Total Gallons pumped from tank (Number only, no text):	400	
Access Risers installed to grade (N/A if not present):	YES	
Tank Condition Good:	YES	
Effluent screen cleaned (N/A if not present):	N/A	
Effluent surfacing around site components (N/A if not checked):		
Were repairs made to the Tank or Tank Components? (if YES explain in comments):	YES	