

R&M Drilling, Inc. LIC#1017078

PO BOX 1329  
VALLEY SPRINGS, CA.  
95252

# Invoice

Date	Invoice #
2/3/2026	3463

Bill To
Tammy Goolsby 4875 Camanche Pkwy Ione, Ca. 95640 209-332-0118

**PAID**  
**03/05/2026**

Description	Amount
WELL INSPECTION	650.00
AMADOR COUNTY SALES TAX	0.00
<b>Total</b>	<b>\$650.00</b>



## Well & Pump Performance Test

Date: 3-3-2026 Property Owner: REALTOR TAMMY Goolsby  
 Property Address/APN#: 4875 Camanche Parkway N Tane CA 95640  
 Well Location: RT REAR of Property Type of well: Domestic Well casing diameter 6"  
 Standing Water level: N/A Pump Type: Sub HP: 1 Voltage: 230 Phase: 1

**PERFORMANCE TEST COMPLETED BY:** John Saramillo

**Well Visual Inspection:**

Casing Size: 6"  
 Well Seal: Good Well Depth: unknown Well Vent: \_\_\_\_\_  
 Comments: \_\_\_\_\_

**Pump Visual Inspection:**

Drop Pipe Size: 1" Tank: 119 bladder Pump Tip: \_\_\_\_\_  
 Pump Setting: unknown Plumbing: poly, copper & pvc  
 Pressure Relief Valve: yes

**NORMAL FULL LOAD AMPS:**

Y 8.2 BLK 8.2 RED 0

**NORMAL SERVICE FACTOR AMPS:**

Y 10.4 BLK 10.4 RED 0

TEST	TOTAL GALLONS	MINITUES	GPM	AMP YEL	AMP BLK	AMP RED	PUMPING WATER LEVEL
0 PSI	2000	100	20	7.82	8.02	.02	unable to
30 PSI	190	10	19	8.18	8.31	.05	measure
60 PSI	150	10	15	8.20	8.25	.06	

VISUAL INSPECTION	FUNCTIONAL	DEFICIENT	NOT OBSERVED
PUMP OPERATION	<u>Good</u>		
ELECTRICAL EQUIP.	<u>Good</u>		
PRESSURE TANK		<u>Bladder Ruptured</u>	
PRESSURE R VALVE	<u>Good</u>		
WATER PIPES		<u>union @ well head</u>	
WELL SEAL	<u>Good</u>		

**COMMENTS:** Well pump pull Good amp load. Bladder tank bladder is Ruptured needs to be Replaced. NO union @ well head. Well produced 2340 Gallons in 2 hrs of pumping. Well system needs few Repairs, other than the Repairs Listed system is in Good working order.



**R & M Drilling**  
**6000 South Worth Rd**  
**Valley Springs, CA 95252**  
**Customer ID: 3017603**

**March 4, 2026**  
**STK2632970:1**  
**Preliminary Coliform Bacteria Analysis**  
**Project Name: 4815 Camanche Parkway**  
**North Ione Ca 95640 - Tammy Gaolsby**  
**System Number: N/A**

**Analytical Results**

ID	Sample Description	Total	Fecal	E. Coli	Units	Method	Prep	Footnote
1	Well Head	<1.0 Absent	---	<1.0 Absent	MPN/100ml	SM 9223B	Quanti Tray 18	

N/R Not Required      MPN Most Probable Number      A/P Absence/Presence      SM 9223B E. Coli specific for Fecal

**Sample Handling Information**

ID	Sample Number	System Number	Sample Type/Reason	Sampler	Employed By	Sampled
1	STK2632970-001	N/A	Source-Other	John Jaramilo	R & M Drilling	2026-03-03 12:05

**QA Information**

ID	Sample Description	CI Total/Free	Temp °C	Started	Finished	Contact	Contacted
1	Well Head	---/---	---	2026-03-03 14:01 TAG	2026-03-04 HK1	N/R	

Analyses were performed using Standard Methods 20th edition. If you have any questions regarding your results, please call.

**This is a Preliminary Report, the Final Report will follow in 14 days.**