



Job #121369

Septic Tank Inspection

Tank Size

1250g

Customer Name

TIM LYNCH

Date

2026-03-27

Address

13983 Santa Rita Drive, Nampa, ID 83686 USA

Water Level

Normal

Inlet Baffle

Intact

Outlet Baffle

Intact

Run-Back

No

Clear Mainline:

Yes

Other Comments

Water level normal, both baffles intact, clear main line, no run back from drain field at time of service.

Technician

Caleb Short